

CISCO *Live!*

Let's go



The bridge to possible

Why You Shouldn't Fear Upgrading Your ACI Fabric


The Handbook!

Takuya Kishida, Technical Leader, Technical Market Engineering
Joey Ristaino, Technical Leader, Technical Market Engineering



Agenda

- Why Upgrade?
- Upgrade Architecture
 - ACI Firmware Upgrade Types
 - Upgrade Architecture – APIC
 - Upgrade Architecture – Switches
 - (Bonus) Upgrade Enhancements
- Best Practices
 - Best Practices Workflow Review
 - Best Practices Configurations
 - “Pre-Upgrade Checklist” Review and Execution
 - “Do’s and Don’ts”

Why Upgrade?




New features, new use cases, new possibilities



And more with NDI (Nexus Dashboard Insight) for ACI 4.2(5) or newer


Get out of the vicious cycle

By knowing the upgrade architecture and best practices



ACI Firmware Upgrade Types


ACI Firmware Upgrade Types



ACI Firmware Upgrade Types (Regular)

 Regular Upgrade


 Software Maintenance Upgrade (SMU)

 EPLD/FPGA Upgrade (Only Switches)

Base OS firmware upgrade

In principle, all APICs and switches should be on the same version

- 1 APIC Upgrade
- 2 Switch Upgrade (through APIC)



Different versions in the same fabric??



In principle, this should be avoided.

What if I cannot finish upgrades in a single upgrade window?


- Available options

APIC firmware

- All APICs must be on the same version

Switch firmware

- Switches can be on different versions **with limited operations.**



Create, update and delete **BDs, EPGs, contracts, L3Outs, VMM domains, Access Policies**



Collect **configuration backups, techsupports**, or troubleshoot with **SPAN**




Physical operations such as enabling disabling **interfaces, replacing a node**

See Upgrade Guide for the complete list:
<https://www.cisco.com/c/en/us/td/docs/dcn/aci/apic/all/apic-installation-aci-upgrade-downgrade/Cisco-APIC-Installation-ACI-Upgrade-Downgrade-Guide/m-operations-allowed-during-mixed-versions-on-cisco-aci-switches.html>


ACI Firmware Upgrade Types (SMU)

5.2(1)



 Regular Upgrade

 Software Maintenance Upgrade (SMU)

 EPLD/FPGA Upgrade (Only Switches)

A patch for a specific defect


No need to upgrade the entire fabric. You can apply it only to APICs or affected switch nodes

1


SMU for all APICs


2

SMU for specific switches (through APIC)



ACI Firmware Upgrade Types (EPLD/FPGA)


 Regular Upgrade

 Software Maintenance Upgrade (SMU)

 EPLD/FPGA Upgrade (Only Switches)

Hardware related firmware

Each ACI switch version has the desired EPLD/FPGA version.
Automatically upgraded via Regular Upgrade through APIC.
➤ No user configurations



APIC Upgrade Architecture

Note: for 4.0 or newer APICs

APIC Upgrade Architecture


Image Upload

- A user uploads the APIC image on one of APICs
- After md5sum check, the image is copied to other APICs

Trigger

Install

Data Conversion
&
Reboot



APIC Upgrade Architecture

Image Upload

Trigger

- Set the target version on all APICs
- APIC1 informs shards on all APICs of upgrades

Install


Data Conversion
&
Reboot

No disruptive operations from this point.
(details in later slides)

Estimated Time

A few min.

Prepare all shards for upgrade



APIC Upgrade Architecture

Image Upload


Trigger

Install

- Install APIC OS in a backup partition
- All APICs perform this in parallel

Data Conversion
&
Reboot

Estimated Time
A few min.



APIC Upgrade Architecture

Image Upload

Trigger

Install

**Data Conversion
&
Reboot**


- Convert user configurations and data to the target version format
- Conversion happens one APIC at a time

6.0(3) or newer requires significantly less time due to an internal enhancement in data conversion

NEW

Estimated Time

Depends on the size of data.
A fair estimation would be 40 min per APIC
(potentially more or less)



ACI Switch Upgrade Architecture



ACI Switch Upgrade Flow

Image Download


- The switch downloads the image from APIC
- The download is via infra TEP

Queuing

Preparation

Reboot

Boot Up



ACI Switch Upgrade Flow

Image
Download

Queuing

- The switch receives approval from APIC
- Controls switches that are upgraded in parallel

Preparation


Since APIC 4.1(1)

- One leaf at a time in each vPC pair
- Not all spines in each pod if graceful option is used

Reboot

Boot Up

No Traffic Impact



ACI Switch Upgrade Flow

Image
Download

Queuing


Preparation

- The switch extracts the image.
- The switch sets the boot var and so on.

Reboot

Boot Up

No Traffic Impact



ACI Switch Upgrade Flow

Image
Download

Queuing

Preparation


Reboot

- Wipe the config and reboot (i.e. clean reboot)
- Traffic failover relies on link failure

Boot Up

- Depends on other conditions such as:
- Link failure detection time on external devices
 - Routing protocol and so on

**< 100 msec Traffic Impact
in the best case**



ACI Switch Upgrade Flow

Image
Download


Queuing

Preparation

Reboot

Boot Up

- Various traffic flow optimizations
- (Continue to next slides)



ACI Switch Upgrade Flow (Boot Up Sequence)

Boot Up

· Various traffic flow optimizations

01

- Bring up fabric links
- Bring up APIC connected down links
- Admin down other down links

02

03


04

05

06

07

No Traffic Flow Change



ACI Switch Upgrade Flow (Boot Up Sequence)

Boot Up

· Various traffic flow optimizations

01

- Bring up fabric links
- Bring up APIC connected down links
- Admin down other down links

02

- An APIC discovers the switch via DHCP/LLDP
- The same TEP IP is assigned

03


04

05

06

07

No Traffic Flow Change



ACI Switch Upgrade Flow (Boot Up Sequence)

Boot Up

· Various traffic flow optimizations

01

- Bring up fabric links
- Bring up APIC connected down links
- Admin down other down links

02

- An APIC discovers the switch via DHCP/LLDP
- The same TEP IP is assigned

03

- ISIS overload mode is activated
 - ✓ ISIS advertises the TEP IP with a large metric
 - ✓ ISIS does not advertise BD mcast groups to join


04

05

06

07

No Traffic Flow Change



ACI Switch Upgrade Flow (Boot Up Sequence)

Boot Up

· Various traffic flow optimizations

01

- Bring up fabric links
- Bring up APIC connected down links
- Admin down other down links

02

- An APIC discovers the switch via DHCP/LLDP
- The same TEP IP is assigned

03

- ISIS overload mode is activated
 - ✓ ISIS advertises the TEP IP with a large metric
 - ✓ ISIS does not advertise BD mcast groups to join


04

- Starts downloading configurations from an APIC

05

06

07



ACI Switch Upgrade Flow (Boot Up Sequence)

Boot Up

· Various traffic flow optimizations

01

- Bring up fabric links
- Bring up APIC connected down links
- Admin down other down links

02

- An APIC discovers the switch via DHCP/LLDP
- The same TEP IP is assigned

03

- ISIS overload mode is activated
 - ✓ ISIS advertises the TEP IP with a large metric
 - ✓ ISIS does not advertise BD mcast groups to join

04

- Starts downloading configurations from an APIC

05

- ISIS multicast overload mode completes (i.e. flood)
- vPC peer is established at the same time


06

ISIS multicast overload timer

- Leaf nodes – Fixed 1min
- Spine nodes – When FTAG tree is created (Fixed 1 min prior to Switch 14.2(1))

07

No Traffic Flow Change



ACI Switch Upgrade Flow (Boot Up Sequence)

Boot Up

· Various traffic flow optimizations

01

- Bring up fabric links
- Bring up APIC connected down links
- Admin down other down links

02

- An APIC discovers the switch via DHCP/LLDP
- The same TEP IP is assigned

03

- ISIS overload mode is activated
 - ✓ ISIS advertises the TEP IP with a large metric
 - ✓ ISIS does not advertise BD mcast groups to join

04

- Starts downloading configurations from an APIC

05

- ISIS multicast overload mode completes (i.e. flood)
- vPC peer is established at the same time


06

- Full configuration has been downloaded
 - ✓ Bring up access links (downlinks)
 - ✓ and vPC ports after vPC restore delay timer expires

07

Ready to receive traffic

- VLANs are deployed
 - For VMM, depends on Resolution Immediacy
- Contracts are deployed
 - Depends on Deployment Immediacy
- Spine-Proxy is ready
- Flood handling (FTAG) is ready



ACI Switch Upgrade Flow (Boot Up Sequence)

Boot Up

· Various traffic flow optimizations

01

- Bring up fabric links
- Bring up APIC connected down links
- Admin down other down links

02

- An APIC discovers the switch via DHCP/LLDP
- The same TEP IP is assigned

03

- ISIS overload mode is activated
 - ✓ ISIS advertises the TEP IP with a large metric
 - ✓ ISIS does not advertise BD mcast groups to join

04

- Starts downloading configurations from an APIC

05


- ISIS multicast overload mode completes (i.e. flood)
- vPC peer is established at the same time

06

- Full configuration has been downloaded
 - ✓ Bring up access links (downlinks)
 - ✓ and vPC ports after vPC restore delay timer expires

07

- ISIS unicast overload mode completes
 - ✓ The TEP IP is advertised with a normal metric



ACI Switch Upgrade with Graceful Option (a.k.a. Graceful Upgrade)

ACI Switch Upgrade with graceful option

Image
Download

Scheduler

Preparation


Reboot

- Wipe the config and reboot (i.e. clean reboot)
- ~~Traffic failover relies on link failure~~

Boot Up

The rest is the same as without graceful option.

Graceful Option is to gracefully isolate the switch before the switch goes down for the upgrade



Enhanced reboot sequence with graceful option

- Graceful option **disabled**

Reboot

1. Wipe the config and reboot (i.e. clean reboot)
2. Traffic failover relies on user configured link failure mechanism


- Graceful option **enabled**

Reboot

1. Put the switch into MMode (Maintenance Mode)
 1. ISIS Overload Mode enabled
 2. Graceful Shutdown on Routing Protocols
 - ✓ Leaf - BGP, EIGRP, OSPF for L3Out
 - ✓ Spine - BGP, OSPF for IPN, GOLF
 3. vPC informs its peer that this switch is going down
 4. LACP sends PDUs with aggregation bit zero (starting from 3.1(2))
 - External devices can exclude the link from the port-channel before the link physically goes down.
 5. Shutdown front panel ports
 - ✓ Leaf - all down links including APIC connected links
2. Wipe the config and reboot (i.e. clean reboot)


Traffic Disruption without Graceful Upgrade

- OSPF DR reboot example



With Graceful Upgrade

- OSPF DR reboot example



GIR and Graceful Upgrade in ACI



Both GIR (Graceful Insertion and Removal) and Graceful Upgrade put the switch in MMode (Maintenance Mode) to isolate the switch from the fabric.

However, the use case for these two features are completely different.

GIR (Graceful Insertion and Removal)

Use Case:

- To isolate a switch for further debugging
- To quickly restore service by isolating a malfunctioning switch

Difference:

- It is not supported to upgrade a switch in MMode via GIR

Serial Number	Model	Pod ID
FDO230...	N9K-C9318CV...	1
FDO230...	N9K-C9318CV...	
FDO232...	N9K-C9318CV...	
FDO232...	N9K-C9318CV...	
FDO232...	N9K-C9318CV...	
FDO232...	N9K-C9318CV...	
FDO232...	N9K-C9318CV...	

Context menu options:

- Edit Node and Rack Names
- Commission
- Decommission
- Maintenance (GIR)**
- Remove From Controller

An upgrade with the graceful option

Use Case:

- To upgrade a switch after isolating the switch

Difference:

- The switch will communicate to APIC and perform an upgrade immediately after the switch was put into MMode.


Advanced Settings

Compatibility Check
 Enforced Unenforced

Graceful Upgrade
 Enforced Unenforced


Run Mode

Auto Firmware Update




Auto Firmware Update for APIC

Use Case 1: APIC Replacement



Use Case 2: Cluster Expansion



Auto Firmware Update for Switches

Enforcing Version Consistency

The screenshot shows the 'Fabric Membership' configuration page. At the top, there are tabs for 'Registered Nodes', 'Nodes Pending Registration', 'Unreachable Nodes', 'Unmanaged Fabric Nodes', and 'Auto Firmware Update'. The 'Auto Firmware Update' tab is selected. Below the tabs, there is a blue information box with a warning icon. The text inside the box reads: 'When Auto Firmware Update on Switch Discovery is enabled, APIC automatically updates the switch firmware for the following scenarios:'. Below this, there is a bulleted list: '• A new switch discovery with a new node ID.', '• A switch replacement with an existing node ID.', and '• An initialization and rediscovering of an existing node.'. Below the list, there is a paragraph: 'If the new switch's node ID is already part of a firmware update group under Admin > Firmware, such as a replacement scenario, the new switch is updated to the target version specified by the update group. Otherwise, it is updated to Default Firmware Version specified by Auto Firmware Update on Switch Discovery.'. Below the information box, there is a green-bordered box containing the configuration options: 'Auto Firmware Update on Switch Discovery: ' and 'Default Firmware Version: n9000-15.2(7f)'. The 'Default Firmware Version' is shown in a dropdown menu.







Fabric > Inventory > Fabric Membership > Auto Firmware Update >=5.1(1)

Admin > Firmware > Infrastructure > Nodes > Enforce Bootscript Version Validation < 5.1(1)

32-bit/64-bit Switch Images

32-bit/64-bit switch images

<https://software.cisco.com>

Cisco Nexus 9000 Series ACI Mode Switch Software 64-bit Release 16.0(2h) aci-n9000-dk9.16.0.2h-cs_64.bin Advisories	01-Mar-2023	2007.44 MB	  
Cisco Nexus 9000 Series ACI Mode Switch Software 32-bit Release 16.0(2h) aci-n9000-dk9.16.0.2h.bin Advisories	01-Mar-2023	1893.29 MB	  

Why?

Scalability

To utilize the most of what switch hardware has to offer.

Which Image?

Depends on the memory size

24G or less -> 32 bit
Otherwise -> 64 bit

Note: Fixed per switch model in ACI Switch 16.0(2)

Feature Differences?

None

Features (scale) are handled based on switch model.
No feature differences specific to image type (32/64 bits).

Upgrade Procedure

Regular One (ex. 4.2 -> 5.2)

0 Upload Images

1. Upload target APIC image to APICs
2. Upload target switch images to APICs

1 APIC Upgrade

1. Upgrade APIC cluster

2 Switch Upgrade (through APIC)

1. Download the switch images from APICs to switches
2. Upgrade switches

Upgrade Procedure

Specific to pre-6.0(2) -> 6.0(2) or later (ex. 5.2.7 -> 6.0.2)

except 5.2(8), 5.3

0 Upload Images

1. Upload target APIC image to APICs
- ~~2. Upload target switch images to APICs~~

Do not upload switch images (16.0(2) or later) until APICs are upgraded.

If your APICs are on 5.2(8), 5.3, no need to worry about this

1 APIC Upgrade

1. Upgrade APIC cluster

2 Switch Upgrade (through APIC)

1. Upload target switch images to APICs
2. Download the switch images from APICs to switches
3. Upgrade switches

ACI Upgrade Guide:

https://www.cisco.com/c/en/us/td/docs/dcn/aci/apic/all/apic-installation-aci-upgrade-downgrade/Cisco-APIC-Installation-ACI-Upgrade-Downgrade-Guide/m-aci-upgrade-downgrade-architecture.html#Cisco_Reference.dita_22480abb-4138-416b-8dd5-ecde23f707b4

Upgrade Procedure

Anything -> 6.0(2) or later (ex. 5.2.7->6.0.4, 6.0.2->6.0.4 etc.)

0 Upload Images

1. Upload target APIC image to APICs
2. Upload target switch images to APICs

1 APIC Upgrade

1. Upgrade APIC cluster





2 Switch Upgrade (through APIC)

1. Upload target switch images to APICs
2. Download the switch images from APICs to switches
3. Upgrade switches

In either case, upload BOTH 32- and 64-bit images to APICs. APICs will pick the appropriate image for each switch.

Upgrade Enhancements

ACI Upgrade Enhancement Quick Summary

		Supported APIC versions 	4.1(1)	4.2(1)	4.2(5)	5.2(1)	5.2(3)	6.0(2)	6.0(3)	Switch version requirements
Upgrade Time Optimization 	Switch Image Pre-download	✓	✓	✓	✓	✓	✓	✓	✓	14.1(1) or later
	Multi-Pod Parallel Switch Upgrade			✓	✓	✓	✓	✓	✓	No requirements
	Unlimited Parallel Switch Upgrade By Default			✓	✓	✓	✓	✓	✓	No requirements
Visibility 	Faster APIC Data Conversion								✓	N/A
	APIC Detailed Install Stage			✓	✓	✓	✓	✓	✓	N/A
	Switch Image Download Progress			✓	✓	✓	✓	✓	✓	14.5(1) or later
Operation Optimization 	Built-in Pre-Upgrade Validation		✓	✓	✓	✓	✓	✓	✓	No requirements
	Pre-Upgrade Validator App					✓	✓	✓	✓	No requirements
	SMU Support					✓	✓	✓	✓	15.2(1) or later
	Auto EPLD/FPGA upgrade					✓	✓	✓	✓	15.2(1) or later
	NXOS to ACI auto conversion via POAP						✓	✓	✓	15.2(3) or later
	Auto Firmware Update for APIC							✓	✓	N/A
	Auto Firmware Update for switches		✓	✓	✓	✓	✓	✓	✓	No requirements

Agenda

- Upgrade Architecture
 - ACI Firmware Upgrade Types
 - Upgrade Architecture – APIC
 - Upgrade Architecture – Switches
 - (Bonus) Upgrade Enhancements
- Best Practices
 - Best Practices Workflow Review
 - Best Practices Configurations
 - “Pre-Upgrade Validation” Review and Execution
 - “Do’s and Don’ts”

ACI Firmware Upgrade Best Practice Checklist

- ✓ Determine Desired Software and Check Support Matrix
- ✓ Review and Implement Best Practice Configurations
- ✓ Discover and Clear any issues raised from “pre-upgrade validations”
- ✓ Review Upgrade Architecture and “do’s and don’ts”

ACI Software Life Cycle

1

Cisco Recommended Software Releases

https://www.cisco.com/c/en/us/td/docs/switches/datacenter/aci/apic/sw/recommended-release/b_Recommended_Cisco_ACI_Releases.html

2

Cisco ACI Release Notes

<https://www.cisco.com/c/en/us/support/cloud-systems-management/application-policy-infrastructure-controller-apic/tsd-products-support-series-home.html>

3

Cisco ACI Upgrade/Downgrade Support Matrix

<https://www.cisco.com/c/dam/en/us/td/docs/Website/datacenter/apicmatrix/index.html>

4



APIC Upgrade/Downgrade Support Matrix

This page provides Cisco APIC software upgrade and downgrade information based on current and target releases. The provided upgrade paths have been tested and validated by Cisco, Cisco partners, or both.

For an overview of the entire fabric upgrade process, including relevant reference and procedure documents, see the [Cisco ACI Upgrade Checklist](#).

For feedback on this tool, send email to apic-docfeedback@cisco.com.

I am upgrading... I am downgrading...

From release

To release

Current release: 3.2(10)

Target release: 4.2(7) [[↗](#)]

Recommended path: Direct path from Current Release. [[Show All](#)]


Determines if Multi-Step Upgrade is Required

ACI Upgrade Overview

5

Review the ACI Upgrade/Downgrade Guide!

https://www.cisco.com/c/en/us/td/docs/dcn/aci/apic/all/apic-installation-aci-upgrade-downgrade/Cisco-APIC-Installation-ACI-Upgrade-Downgrade-Guide/m-aci-firmware-upgrade-overview.html#id_48185



The screenshot shows a web interface for Cisco documentation. On the left is a navigation menu with items like 'Book Contents', 'Book Title Page', 'Trademarks', 'New and Changed Information', 'Cisco ACI Long-Lived and Short-Lived Releases', 'Installing or Recovering Cisco APIC Images', 'ACI Firmware Upgrade Overview' (highlighted), 'ACI Upgrade Architecture', 'Operations Allowed During Mixed Versions on Cisco ACI Switches', and 'Pre-Upgrade Checklists'. The main content area has a search bar at the top with the text 'Find Matches in This Book' and a 'Save' button. The title of the page is 'Workflow to Upgrade the Cisco ACI Fabric'. Below the title is a paragraph explaining that Cisco APIC centrally manages the upgrade for the entire fabric. This is followed by a numbered list of steps: 1. Pick your target APIC and ACI switch versions. (with sub-points a, b, and c), and 2. See the APIC Upgrade/Downgrade Support Matrix for the supported upgrade paths from your current version. (with sub-point a).

CIMC Version Compatibility

6

Option 1: Support Matrix <https://www.cisco.com/c/dam/en/us/td/docs/Website/datacenter/apicmatrix/index.html>

APIC Software Upgrade/Downgrade Support Matrix

This page provides Cisco APIC software upgrade and downgrade information based on current and target releases. The provided upgrade paths have been tested and validated by Cisco, Cisco partners, or both.

For an overview of the entire fabric upgrade process, including relevant reference and procedure documents, see the [Cisco ACI Upgrade Checklist](#).

For feedback on this tool, send email to apic-docfeedback@cisco.com.

I am upgrading... I am downgrading...

From release

To release

➔

Recommended software for target release:

This is a list of **recommended** releases, not the only supported releases for your target APIC release. Check the specific software's *Release Notes* and documentation for other release versions supported for your target APIC release.

- Cisco NX-OS ACI-mode version: 15.2(7)
- Cisco Nexus Dashboard Orchestrator: 3.7(2g)
- Cisco ACI Virtual Edge version: 3.2(4b)
- Cisco IMC version: UCS C220/C240 M5 (APIC-L3/M3): 4.1(3f); UCS C220/C240 M4 (APIC-L2/M2): 4.1(2g); UCS C220/C240 M3 (APIC-L1/M1): 3.0(4l)
- Canonical version: Ussuri

Option 2: APIC Release Note <https://www.cisco.com/c/en/us/support/cloud-systems-management/application-policy-infrastructure-controller-apic/tsd-products-support-series-home.html>

Release Notes

Cisco APIC Release Notes

- [Cisco Application Policy Infrastructure Controller Release Notes, Release 6.0\(2\)](#)
- [Cisco Application Policy Infrastructure Controller Release Notes, Release 6.0\(1\)](#)
- [Cisco Application Policy Infrastructure Controller Release Notes, Release 5.2\(7\)](#)
- [Cisco Application Policy Infrastructure Controller Release Notes, Release 5.2\(6\)](#)

➔

CIMC HUU ISO

- 4.2(3b) CIMC HUU ISO (recommended) for UCS C220/C240 M5 (APIC-L3/M3)
- 4.2(2a) CIMC HUU ISO for UCS C220/C240 M5 (APIC-L3/M3)
- 4.1(3f) CIMC HUU ISO for UCS C220/C240 M5 (APIC-L3/M3)
- 4.1(3d) CIMC HUU ISO for UCS C220/C240 M5 (APIC-L3/M3)
- 4.1(3c) CIMC HUU ISO for UCS C220/C240 M5 (APIC-L3/M3)
- 4.1(2k) CIMC HUU ISO (recommended) for UCS C220/C240 M4 (APIC-L2/M2)

ACI Firmware Upgrade Best Practice Checklist

- ✓ Determine Desired Software and Check Support Matrix
- ✓ Review and Implement Best Practice Configurations
- ✓ Discover and Clear any issues raised from “pre-upgrade validations”
- ✓ Review Upgrade Architecture and “do’s and don’ts”

Back Up Configuration



Back Up Configuration with AES File Encryption



- The AES passphrase that generates the encryption keys cannot be recovered or read by an ACI administrator or any other user. The AES passphrase is not stored. **Copy your passphrase somewhere safe!**
- Setup automatic backups on a scheduler to maintain a consistent and up-to-date backup at all times. **Always export it to a remote location.**
- In case of upgrade failure, AES backup can be used to **recover the system non-disruptively** as worst case scenario.

Setting Global AES Encryption allows all the secure properties of the configuration (like credentials) to be successfully imported when restoring the fabric

APIC

System Tenants Fabric Virtual Networking Apps Integrations

QuickStart | Dashboard | Controllers | System Settings | Smart Licensing | Faults | Config Zones | Events | Audit Log | Active Sessions

System Settings

Global AES Encryption Settings for all Configuration Import and Export

Policy History

These encryption settings apply to all the configuration imports and exports within APIC.

Properties

Enable Encryption:

Encrypted Passphrase: \$6\$ZTELPNUNJQWLO\$emrx5VwE9.dI6qbsNg40eBb0ki/3nTLKun2oNQsb1.Niz/9JGk1705k3dM

Key Configured: Yes

Passphrase:

Confirm Passphrase:

Time Generated (date): 2021-09-16T12:46:43.380+02:00

Pre ACI v4.0.1 Setting Location:

Admin > AAA > AES Encryption Passphrase and Keys for Config Export (and Import)

ACI v4.0.1 and later Location:


System > System Settings > Global AES Passphrase Encryption Settings

Technote For Import/Export:

https://www.cisco.com/c/en/us/td/docs/switches/datacenter/aci/apic/sw/kb/b_KB_Using_Import_Export_to_Recover_Config_States.html

Switch Upgrade Groups

ACI Firmware Upgrade Best Practice 101



ACI is a solution to manage multiple switches as if it's one huge switch

- APIC (i.e. SUP of the fabric) can be upgraded non-disruptively.
- Each switch (i.e. modules of the fabric) can intelligently choose appropriate switch nodes for non-disruptive traffic flow

Always keep hardware redundancy to achieve zero-to-minimum traffic disruption

1. Upgrade **Green** switch groups
2. Upgrade **Blue** switch groups

Switch Upgrade Advanced Options

Upgrade Group

- Name
- Node ID List
- Target Firmware Version
- Scheduler
- **Ignore Compatibility Check**
- Graceful option
- Run Mode

Rule of Thumb

Change defaults only when you must.

- **Compatibility Check** (default: Enforced)
Only unenforce in a lab where you would like to ignore the supported upgrade path.

- **Graceful Upgrade** (default: Unenforced)
Only enforce when sub-100ms routing protocol convergence is required.
Never enforce this when hardware redundancy is lacking. (single spine/leaf pod)

- **Run Mode** (default < 5.1: pause upon upgrade failure
(default >= 5.1: don't pause upon upgrade failure)

By default, APIC scheduler will stop putting new switches into queue if

- a) APIC cluster is not fully-fit
- b) The upgrade of previous switches in the same upgrade group failed.

Ex.) You have 20 leaves in a group. If 1 fails, it will pause all remaining switches that are still queued. If other 19 leaves already started upgrade procedure, those will not be paused.

Later Releases, ie: 5.2

Edit > Version Selection > Advanced Settings

Advanced Settings

Compatibility Check
 Enforced Unenforced


Graceful Upgrade
 Enforced Unenforced

Run Mode
 Do not pause on failure & cluster health Pause upon upgrade failure


IS-IS Metric Policy for Multi-Pod and Multi-Site

Helpful Tips for Multi-Pod / Multi-Site

ISIS Metric Policy Configuration




- Default fabric wide IS-IS metric is set at 63 (max value)
- During upgrade, spines set the overload mode while policy is being downloaded.
- If fabric-wide value is already at max, the overload functionality is ineffective.
- This can create unexpected traffic interruption if leaf sends traffic to a spine which is not fully upgraded.




Settings > ISIS Policy (Default Config)

Helpful Tips for Multi-Pod / Multi-Site

ISIS Metric Policy Configuration



- By Lowering the Value, Remote POD TEP Routes will be preferred through the remaining spines in each POD.
- Once Overload is completed, the spine which was upgraded will advertise these routes using the metric configured.
- This results in ECMP between all spines after the upgrade has completed.




Settings > ISIS Policy

ACI Firmware Upgrade Best Practice Checklist

- ✓ Determine Desired Software and Check Support Matrix
- ✓ Review and Implement Best Practice Configurations
- ✓ Discover and Clear any issues raised from “pre-upgrade validations”
- ✓ Review Upgrade Architecture and “do’s and don’ts”

Does your fabric look like this?



Fault Counts by Domain

Hide Acknowledged Faults

Hide Delegated Faults

SYSTEM WIDE	164	1858	31173	6205
Access	145	1789	5	82
External	0	0	0	4995
Framework	0	2	0	0
Infra	19	62	1270	1126
Management	0	4	5	0
Security	0	0	214	0
Tenant	0	1	29679	2
Apps	0	0	0	0


Tenants with Health ≤ 99

Name Health Score

scale_vpc20	Warning
scale_vpc30	Warning
scale_vpc40	Warning
scale_vpc50	Warning
Tenant_1	Critical
Tenant_10	Critical
Tenant_100	Critical
Tenant_101	Critical

Faults, and the Impact on Upgrades


- Faults can be raised if there is an overlap, or invalid config.
- After an upgrade the switch requests it's configuration "fresh" from APIC. This is the "stateless" behavior of ACI.
- If Logical Config (APIC) has conflicts, the "faulted" config can get pushed before the previously working config.



L2 Port Config (F0467 port-configured-as-13)
L3 Port Config (F0467 port-configured-as-12)
Config On APIC Connected Port (F0467 port-configured-for-apic)
etc . . .


Pre-Upgrade Validation

APIC 3.2, 4.0, 4.1




Screenshot of a warning message titled "Schedule Controller Upgrade". The message contains a yellow warning icon and text: "The fabric has 2 Critical Faults and 30 Major Faults. It's recommended that these faults are resolved before performing a controller upgrade. All unsupported features must be disabled before downgrade to avoid unpredictable behavior."

APIC 4.2(1) - 4.2(3)



Screenshot of a warning message titled "Schedule Controller Upgrade". The message contains a red error icon and text: "Migration cannot proceed due to 1 active critical config faults. It's recommended that these faults are resolved before performing a controller upgrade. All unsupported features must be disabled before downgrade to avoid unpredictable behavior. Click Here for more info." Below the text is a checkbox: " I understand there are active faults on the system which can lead to unexpected issues, proceed with the upgrade."

APIC 4.2(4)



Screenshot of a warning message titled "Schedule Controller Upgrade". The message contains a red error icon and text: "Infra:Following nodes are not in VPC: ['102', '103', '101', '104']". Below this is a text box containing the same text. Further down, it says: "It's recommended that these faults are resolved before performing a controller upgrade. All unsupported features must be disabled before downgrade to avoid unpredictable behavior." At the bottom is a checkbox: " I understand there are active faults on the system which can lead to unexpected issues, proceed with the upgrade."

- Prior to 4.2, the APIC upgrade simply warned about the number of all critical and major faults
- On 4.2(1) - 4.2(3), the APIC upgrade warned about
 - ✓ config related critical faults
 - ✓ some specific faults that are known to cause issues during upgrades.
- On 4.2(4), the APIC upgrade warns about
 - ✓ config related critical faults
 - ✓ some specific faults that are known to cause issues during upgrades
 - ✓ A few nonoptimal configurations that may disrupt traffic during the upgrade.
- Additional validation items are being added on each release.

Pre-Upgrade Validation – Script

<https://github.com/datacenter/ACI-Pre-Upgrade-Validation-Script>

```
[Check 1/36] APIC Target version image and MD5 hash...
Checking f2-apic1.....

[Check 2/36] Target version compatibility...
[Check 3/36] Gen 1 switch compatibility...
[Check 4/36] Remote Leaf Compatibility... No Remote Leaf Found
[Check 5/36] APIC CIMC Compatibility...
[Check 6/36] APIC Cluster is Fully-Fit...
[Check 7/36] Switches are all in Active state...
[Check 8/36] NTP Status...
[Check 9/36] Firmware/Maintenance Groups when crossing 4.0 Release... Versions not applicable
[Check 10/36] Features that need to be Disabled prior to Upgrade...
Feature      Name           Status  Recommended Action
-----
App Center   Policy Viewer  active  Disable the app
Config Zone  test          Locked  Change the status to "Open" or remove the zone

[Check 11/36] Switch Upgrade Group Guidelines... No upgrade groups found!
[Check 12/36] APIC Disk Space Usage (F1527, F1528, F1529 equipment-full)...
[Check 13/36] Switch Node /bootflash usage... all below 50%
[Check 14/36] Standby APIC Disk Space Usage... No standby APIC found
[Check 15/36] APIC SSD Health (F2731 equipment-wearout)...
[Check 16/36] Switch SSD Health (F3073, F3074 equipment-flash-warning)...
[Check 17/36] Config On APIC Connected Port (F0467 port-configured-for-apic)...
[Check 18/36] L3 Port Config (F0467 port-configured-as-l2)...
[Check 19/36] L2 Port Config (F0467 port-configured-as-l3)...
[Check 20/36] L3Out Subnets (F0467 prefix-entry-already-in-use)...
[Check 21/36] BD Subnets (F1425 subnet-overlap)...
[Check 22/36] BD Subnets (F0469 duplicate-subnets-within-ctx)...
[Check 23/36] VMM Domain Controller Status...
[Check 24/36] VMM Domain LLDP/CDP Adjacency Status... No LLDP/CDP Adjacency Failed Faults Found
```

The goal of the script

To be able to apply the latest validations on any APIC versions via a script

Why the script may be a better choice?:

- Supports older versions – available for everyone!
- Always has the latest checks
- With Github account, you can submit issues or features directly



Both app and script are fully supported by TAC

Pre-Upgrade Validation – Script (Preferred)

```
admin@apic1:techsupport> python aci-preupgrade-validation-script.py
==== 2021-11-16T08-45-58-0500 ====
```

```
Enter username for APIC login      : admin
Enter password for corresponding User :
```

User Enters Credentials

Checks that require login leverage this input

```
Checking current APIC version (switch nodes are assumed to be on the same version)...3.2(10e)
```

```
Gathering APIC Versions from Firmware Repository...
```

```
[1]: aci-apic-dk9.5.2.7g.bin
```

User Selects Target Version

Checks that require target version leverage this input.

```
What is the Target Version?      : 1
```

```
You have chosen version "aci-apic-dk9.5.2.7g.bin"
[Check 1/37] APIC Target version image and MD5 hash...
Checking fab3-apic1.....
```

```
[Check 2/37] Target version compatibility...
[Check 3/37] Gen 1 switch compatibility...
```

```
. . .
. . .
. . .
. . .
. . .
```

Failure Details are Provided

Issue should be corrected (Script Re-Run to validate) before performing upgrade.

```
[Check 19/37] L2 Port Config (F0467 port-configured-as-l3)...
```

Fault	Pod	Node	Tenant	AP	EPG	Port	Recommended Action
-------	-----	------	--------	----	-----	------	--------------------

----	---	----	-----	--	---	----	-----
------	-----	------	-------	----	-----	------	-------

F0467	pod-1	node-101	jr	ap1	epg1	eth1/6	Resolve the conflict by removing this config or other configs using this port as L3
-------	-------	----------	----	-----	------	--------	---

FAIL - OUTAGE WARNING!!

DONE
PASS
PASS
PASS

Pre-Upgrade Validation – Script (Preferred)

```
[Check 32/37] BGP Peer Profile at node level without Loopback... PASS
[Check 33/37] L3Out Route Map import/export direction... PASS
[Check 34/37] Intersight Device Connector upgrade status... Connector reporting InternalServerError, Non-Upgrade issue PASS
[Check 35/37] EP Announce Compatibility... PASS
[Check 36/37] Eventmgr DB size defect susceptibility... PASS
[Check 37/37] Contract Port 22 Defect Check... PASS
```

=== Summary Result ===

```
PASS : 28
FAIL - OUTAGE WARNING!! : 4
FAIL - UPGRADE FAILURE!! : 2
MANUAL CHECK REQUIRED : 1
N/A : 2
ERROR !! : 0
TOTAL : 37
```

Summary is Provided

All "FAIL" Categories need remediation.
Detailed Recommendations to Remediate are
in the Upgrade Guide!

Log Bundle is Created

Upload this to any TAC Case if Necessary.

Pre-Upgrade Check Complete.

Next Steps: Address all checks flagged as FAIL, ERROR or MANUAL CHECK REQUIRED

Result output and debug info saved to below bundle for later reference.

Attach this bundle to Cisco TAC SRs opened to address the flagged checks.

Result Bundle: /data/techsupport/Scripts/pre-upgrade/preupgrade_validator_2021-11-16T08-45-58-0500.tgz

Nexus Dashboard Insights (Optional)

Analysis Details - Pre-Upgrade-Check-522

Sep 21st 2021, 3:44 PM - Sep 28th 2021, 3:44 PM Barcelona

Analysis Summary Completed

Site Summary

SITE	SITE FIRMWARE	SITE TARGET FIRMWARE
Barcelona	5.2(1g)	5.2(2e)

Node Summary

SELECTED NODES	NODE FIRMWARE	NODE TARGET FIRMWARE
4 • Leafs (2) • Spines (1) • Other	4 • 5.2(1g) (1) • 15.2(1g) (3)	15.2(2e)

Selected path

1 Sites

Current FW 5.2(1g)

3 Nodes

Current FW 15.2(1g)

1 Pre-Update Checks Warning

View Analysis Details

1 Pre-Update Checks Warning

View Analysis Details

Benefit of Nexus Insights
Does both a pre-check and a post-check to alert on effects and changes in the upgrade window

Analysis Details - Pre-Upgrade-Check-522

Overview Pre-Update Analysis **Post-Update Delta Analysis**

Post-Update Summary

STATUS: 3 Nodes of 3 Updated

ANALYSIS LAST RAN: Sep 27 2021 06:21:38

General

Sep 27 2021 01:52:49.116 PM

Health Delta Policy Delta Operational Delta

Anomaly Count

Critical	Major	Minor	Warning	Info	Total
0	5	3	94	33	169

Analysis Details - Pre-Upgrade-Che... Barcelona

Potential Release Defects

Severity	Category	Title	Description
Minor	bug	CSCvs97029	All the external prefixes from VRF-A could be leaked to VRF-C even when an inter-VRF ESG leak route is configured for a specific prefix.
Minor	bug	CSCv99966	A SPAN session with the source type set to "Routed-Outside" goes down. The SPAN configuration is pushed to the anchor or non-anchor nodes, but the interfaces are not pushed due to the following fault: "Failed to configure SPAN with source SpanFL3out due to Source IntConn not available".

Sep 27 2021 06:21:38.969 PM

0d 4hr 28m 49s

- Pre-Update Verifications and Alerting
- Detailed list of bugs addressed in the upgrade
- Post-upgrade Delta analysis of Anomalies, Edits and Operations changes in the upgrade process

ACI Firmware Upgrade Best Practice Checklist



Determine Desired Software and Check Support Matrix



Review and Implement Best Practice Configurations



Discover and Clear any issues raised from “pre-upgrade validations”



Review Upgrade Architecture and “Do’s and Don’ts”

Do's and Don'ts

If at any point in time you believe the upgrade/downgrade has either stalled or failed, follow the guidelines below:

- Do View the APIC Faults and Installer Logs.
- Do Collect the Tech Support Files.
- Do Contact Cisco TAC if Needed.



```
admin@apic1:logs> pwd
/firmware/logs
admin@apic1:logs> ls -l
2021-04-15T07:42:57-50
2021-05-28T10:18:33-50
admin@apic1:logs> ls -l ./2021-05-28T10:18:33-50
atom_installer.log
insieme_4x_installer.log

leaf101# pwd
/mnt/pss
leaf102# ls installer_detail.log
installer_detail.log
```



```
admin@apic1:~> techsupport local
```




Do's and Don'ts

If at any point in time you believe the upgrade/downgrade has either stalled or failed, it is critical that you do not take any of the actions listed below:

Don't reload any APIC in the cluster manually.

Don't decommission any APIC in the cluster.

Don't change the firmware target version back to the original version.





Final Tip

You've read the "Do's and Don'ts"...

When in Doubt,
Contact Cisco Support



With Proper Backups, Recovery is Always an Option

ACI Firmware Upgrade Best Practice Checklist



Determine Desired Software and Check Support Matrix



Review and Implement Best Practice Configurations



Discover and Clear any issues raised from “pre-upgrade validations”



Review Upgrade Architecture and “do’s and don’ts”

Key points to remember

- Always make sure you are performing a supported upgrade.
- Best Practice Configuration and Backups are Critical to Success
- ACI Pre-Upgrade Validations will prevent known issues from impacting the upgrade.
- Never perform a disruptive procedure during an upgrade without help from Cisco.

Reference

- Cisco APIC Installation and ACI Upgrade and Downgrade Guide
<https://www.cisco.com/c/en/us/td/docs/dcn/aci/apic/all/apic-installation-aci-upgrade-downgrade/Cisco-APIC-Installation-ACI-Upgrade-Downgrade-Guide.html>
- Cisco ACI Upgrade Checklist
<https://www.cisco.com/c/en/us/td/docs/switches/datacenter/aci/apic/sw/kb/Cisco-ACI-Upgrade-Checklist.html>
- Cisco APIC Release Notes
<https://www.cisco.com/c/en/us/support/cloud-systems-management/application-policy-infrastructure-controller-apic/tsd-products-support-series-home.html>
- Release Notes for Cisco Nexus 9000 Series Switches in ACI Mode
<https://www.cisco.com/c/en/us/support/switches/nexus-9000-series-switches/products-release-notes-list.html>
- Getting Started Guide (NX-OS to ACI POAP Auto-conversion)
<https://www.cisco.com/c/en/us/td/docs/dcn/aci/apic/5x/getting-started/cisco-apic-getting-started-guide-52x/fabric-initialization-52x.html#d5018e3247a1635>

Reference


- Cisco APIC Installation and ACI Upgrade / Downgrade Guide
<https://www.cisco.com/c/en/us/td/docs/dcn/aci/apic/all/apic-installation-aci-upgrade-downgrade/Cisco-APIC-Installation-ACI-Upgrade-Downgrade-Guide.html>
- Cisco ACI Upgrade Checklist
<https://www.cisco.com/c/en/us/td/docs/switches/datacenter/aci/apic/sw/kb/Cisco-ACI-Upgrade-Checklist.html>
- Cisco APIC Release Notes
<https://www.cisco.com/c/en/us/support/cloud-systems-management/application-policy-infrastructure-controller-apic/tsd-products-support-series-home.html>
- Release Notes for Cisco Nexus 9000 Series Switches in ACI Mode
<https://www.cisco.com/c/en/us/support/switches/nexus-9000-series-switches/products-release-notes-list.html>
- Cisco ACI Upgrade Matrix
<https://www.cisco.com/c/dam/en/us/td/docs/Website/datacenter/apicmatrix/index.html>
- Pre-Upgrade Validation Script
<https://github.com/datacenter/ACI-Pre-Upgrade-Validation-Script>



The bridge to possible

Thank you

CISCO *Live!*



The Cisco Live! logo features the word "CISCO" in a bold, black, sans-serif font, followed by "Live!" in a black, cursive script font. The background of the entire image is a vibrant, multi-colored abstract pattern of overlapping, wavy bands in shades of red, orange, yellow, green, and blue, creating a sense of motion and energy.

CISCO *Live!*

Let's go