

The background features a vibrant, multi-colored abstract design. On the left, there are overlapping, wavy bands of color in shades of orange, red, and yellow. On the right, a bright white light source emits a series of sharp, radiating lines in various colors, including blue, green, and yellow, creating a sunburst effect.

**CISCO** *Live!*

Let's go

#CiscoLive



The bridge to possible

# High Availability Design with Cisco Catalyst 9800 Wireless Controllers

Business Resiliency with always-on Wireless

Justin Loo, Technical Marketing Engineer  
BRKEWN-2846

cisco *Live!*

#CiscoLive

# Cisco Webex App


## Questions?

Use Cisco Webex App to chat with the speaker after the session

## How

- 1 Find this session in the Cisco Live Mobile App
- 2 Click “Join the Discussion”
- 3 Install the Webex App or go directly to the Webex space
- 4 Enter messages/questions in the Webex space

Webex spaces will be moderated by the speaker until June 9, 2023.



<https://cicolive.ciscoevents.com/cicolivebot/#BRKEWN-2846>

# About Me



## ▶ Fields of Expertise (3 Years at Cisco)

Cisco Catalyst 9800 Wireless LAN Controller, Wireless Assurance and Automation

## ▶ Personal Life

Born and raised in Southern California, University of California Los Angeles Alum

## ▶ Hobbies

Triathlon, Trying new foods, Traveling, Watching movies



Why should I  
care about High  
Availability?

# Agenda

1. **Wireless Controller Redundancy**
  - SSO and N+1 High Availability
  - Gateway Check capability
  - Standby Monitoring
2. **Upstream Switch Redundancy**
  - StackWise Pair and HSRP Topologies
3. **Link Level Redundancy**
  - LAG ON, LACP, PAGP
  - Multi-chassis LAG
4. **Access Point Link Redundancy**
  - Power over Ethernet Redundancy
  - LAG
5. **Controller Software Upgrades**
  - N+1 Site Based Hitless Upgrade
  - In Service Software Upgrade (ISSU)
6. **Software Patching Capabilities**
  - Software Maintenance Updates, AP Service Packs and Device Packs

# Agenda


1. Wireless Controller Redundancy
  - SSO and N+1 High Availability
  - Gateway Check capability
  - Standby Monitoring
2. Upstream Switch Redundancy
  - StackWise Pair and HSRP Topologies
3. Link Level Redundancy
  - LAG ON, LACP, PAGP
  - Multi-chassis LAG

# Agenda

4. Access Point Link Redundancy
  - Power over Ethernet Redundancy
  - LAG
5. Controller Software Upgrades
  - N+1 Site Based Hitless Upgrade
  - In Service Software Upgrade (ISSU)
6. Software Patching Capabilities
  - Software Maintenance Updates, AP Service Packs and Device Packs

# Cisco's Complete Wi-Fi 6E And Wi-Fi 6 Wireless Stack

Enabling next-generation mobility powered by Wi-Fi 6/6E



Cisco Catalyst™ 9800 Series  
Wireless Controllers



Cisco Catalyst 9100  
Access Points



Managed by  
Cisco DNA Center



Translate business intent into network policy and capture actionable insights



Digitized by  
Cisco Spaces


















Digitize people, spaces, and things

Full-stack network intelligence




# How long can my network be down?

★ Catalyst 9800 controller differentiation

	Controller Fault	Controller and AP S/W update	Image Upgrade
<b>Standalone</b> 	<ul style="list-style-type: none"> <li>10s of minutes for AP and client recovery</li> </ul> 	<ul style="list-style-type: none"> <li>Zero-downtime with SMU and APSP</li> </ul>  	<ul style="list-style-type: none"> <li>Tens of minutes for AP and client recovery</li> </ul> 
<b>N+1 HA</b> 	<ul style="list-style-type: none"> <li>Noticeable Outage to clients and APs</li> </ul> 	<ul style="list-style-type: none"> <li>Zero-downtime with SMU and APSP</li> </ul>  	<ul style="list-style-type: none"> <li>No Outage to APs and Clients</li> <li>Automated Orchestration from Cisco DNA Center</li> </ul>  
<b>SSO Pair</b> 	<ul style="list-style-type: none"> <li>Sub-second AP and client recovery</li> </ul> 	<ul style="list-style-type: none"> <li>Zero-downtime with SMU and APSP</li> </ul>  	<ul style="list-style-type: none"> <li>In Service Software Upgrade (ISSU)!</li> <li>Automated from device and Cisco DNA Center</li> </ul>  

# High Availability

## Reducing downtime for Upgrades and Unplanned Events





# Redundancy Feature Comparison

Functionality	AireOS	9800
SSO	Yes	Yes
N+1	Yes	Yes
RMI	Yes	Yes
Dual Active Detection	Yes	Yes
Recovery Mode	Yes	Yes
Default GW Check	Yes	Yes
LACP, PAGP with SSO	No	Yes
SMU for controller patching	No	Yes
APSP for AP Patching	No	Yes
Per-site, per-model AP Patching	No	Yes
AP device pack	No	Yes
ISSU	No	Yes
N+1 Rolling AP Upgrade	Needs Prime, Manual	Yes



For your  
reference

# Resiliency Feature Matrix

Functionality		EWC on AP	Embedded controller on 9K	9800-L	9800-40	9800-80	9800-CL PVT Cloud	9800-CL Public Cloud
Unplanned Events	SSO	No	Supported	Supported	Supported	Supported	Supported	No
	SMU	Supported	Supported	Supported	Supported	Supported	Supported	Supported
Infrastructure updates	APSP	Supported	Supported	Supported	Supported	Supported	Supported	Supported
	APSP Per-site	No	Supported	Supported	Supported	Supported	Supported	Supported
	APDP	Supported	Supported	Supported	Supported	Supported	Supported	Supported
Image Upgrade	ISSU	No	No	Supported	Supported	Supported	Supported	No
	N+1 Rolling AP Upgrade	Supported	Supported	Supported	Supported	Supported	Supported	Supported

# Unplanned events

## Device and network interruptions




# 1. Wireless Controller Redundancy

# N+1 Redundancy

# N+1 Redundancy

- Single C9800 serve as backup for N number of controllers
- Secondary WLC can be different model and software version
- Secondary WLC can be on different subnet
- Upon failover, APs will need to join the Secondary, and clients re-authenticate
- APs can be configured to automatically fallback to Primary
- Stateless Redundancy → Need to keep configurations between Primary and Secondary in synch



AP failover takes ~45-60 seconds

# N+1 Redundancy Configuration

Can be configured via 2 methods

AP Join Profile

Statically on the APs

Recommended to use ONLY ONE of the methods

# Configuration via AP Join Profile

Edit AP Join Profile

General

Client

CAPWAP

AP

Management

Security

ICap

QoS

High Availability

Advanced

CAPWAP Timers

Fast Heartbeat Timeout(sec)\*

1

Heartbeat Timeout(sec)\*

30

Discovery Timeout(sec)\*

10

Primary Discovery Timeout(sec)\*

120

Primed Join Timeout(sec)\*

0

Retransmit Timers

Count\*

5

Interval (sec)\*

3

AP Fallback to Primary ⓘ

Enable

☒

Backup Primary Controller

Name

C9800-Secondary

IPv4/IPv6 Address

10.10.120.1

Backup Secondary Controller

Name

C9800-Tertiary

IPv4/IPv6 Address

10.10.210.1

Allows APs to fallback to the Primary WLC upon recovery

CISCO *Live!*

#CiscoLive

BRKEWN-2846

© 2023 Cisco and/or its affiliates. All rights reserved. Cisco Public

19



# Configuration via AP Join Profile

Edit AP Join Profile

General

Client

CAPWAP

AP

Management

Security

ICap

QoS

High Availability

Advanced

CAPWAP Timers

Fast Heartbeat Timeout(sec)\*

1

Heartbeat Timeout(sec)\*

30

Discovery Timeout(sec)\*

10

Primary Discovery Timeout(sec)\*

120

Primed Join Timeout(sec)\*

0

Retransmit Timers

Count\*

5

Interval (sec)\*

3

AP Fallback to Primary

Enable

Backup Primary Controller

Name

C9800-Secondary

IPv4/IPv6 Address

10.10.120.1

Backup Secondary Controller

Name

C9800-Tertiary

IPv4/IPv6 Address

10.10.210.1

Secondary WLC hostname and IP address

# Configuration via AP Join Profile

Edit AP Join Profile

General

Client

CAPWAP

AP

Management

Security

ICap

QoS

High Availability

Advanced

CAPWAP Timers

Fast Heartbeat Timeout(sec)\*

1

Heartbeat Timeout(sec)\*

30

Discovery Timeout(sec)\*

10

Primary Discovery Timeout(sec)\*

120

Primed Join Timeout(sec)\*

0

Retransmit Timers

Count\*

5

Interval (sec)\*

3

AP Fallback to Primary

Enable☒

Backup Primary Controller

Name

C9800-Secondary

IPv4/IPv6 Address

10.10.120.1

Backup Secondary Controller

Name

C9800-Tertiary

IPv4/IPv6 Address

10.10.210.1

Tertiary WLC hostname and IP address

# Configuration via AP Join Profile

Edit AP Join Profile

General

Client

CAPWAP

AP

Management

Security

ICap

QoS

High Availability

Advanced

CAPWAP Timers

Fast Heartbeat Timeout(sec)\*1

Heartbeat Timeout(sec)\*30

Discovery Timeout(sec)\*10

Primary Discovery Timeout(sec)\*120

Primed Join Timeout(sec)\*0

Retransmit Timers

Count\*5

Interval (sec)\*3

AP Failback to Primary

Enable☒

Backup Primary Controller

NameC9800-Secondary

IPv4/IPv6 Address10.10.120.1

Backup Secondary Controller

NameC9800-Tertiary

IPv4/IPv6 Address10.10.210.1

Required to be a non-zero config

# N+1 Redundancy: Timers

The screenshot shows the 'Edit AP Join Profile' configuration page. The 'CAPWAP' tab is selected, and the 'High Availability' sub-tab is active. Under 'CAPWAP Timers', five fields are highlighted with red boxes: 'Fast Heartbeat Timeout(sec)\*' (0), 'Heartbeat Timeout(sec)\*' (30), 'Discovery Timeout(sec)\*' (10), 'Primary Discovery Timeout(sec)\*' (120), and 'Primed Join Timeout(sec)\*' (0). Under 'Retransmit Timers', two fields are highlighted with red boxes: 'Count\*' (5) and 'Interval (sec)\*' (3).

Section	Parameter	Value
CAPWAP Timers	Fast Heartbeat Timeout(sec)*	0
	Heartbeat Timeout(sec)*	30
	Discovery Timeout(sec)*	10
	Primary Discovery Timeout(sec)*	120
	Primed Join Timeout(sec)*	0
Retransmit Timers	Count*	5
	Interval (sec)*	3

**Fast heartbeats** are dedicated packets to check the availability of Primary WLC and accelerate the failure detection and hence AP failover > 30-45 sec

1-10s (default is 0 = disabled). Dedicated keepalives to detect WLC failure

1-30s (default is 30). Regular CAPWAP keepalives

1-10s (default is 10). Time AP waits to process received discoveries

30-3000s (default is 120). Time AP would check on the Primary

120-43200s (default is 0 = disabled). Time AP tries to join only P/S/T

3-8 (default is 5)

2-5s (default is 3)

# Verifying the AP Configuration

```
SITE4-9162-1# show capwap client ha
fastHeartbeatTmr(sec)    1 (enabled)
primaryDiscoverTmr(sec) 120
primaryBackupWlcIp       10.10.120.1
primaryBackupWlcName     C9800-Secondary
secondaryBackupWlcIp     10.10.210.1
secondaryBackupWlcName   C9800-Tertiary
DHCP renew try count    0
Fwd traffic stats get   58
Fast Heartbeat sent     58
Discovery attempt       0
Backup WLC array:
```


Settings can only be verified via the AP CLI



# Configuration via the AP

Configuration > Wireless > Access Points

▼ All Access Points

Total APs : 7 

AP Name	AP Model	S
SITE3-9120-1	C9120AXI-B	2
SITE4-9120-1	C9120AXI-B	2
SITE2-9120-2	C9120AXI-B	2
SITE2-9166-1	CW9166I-B	3
SITE1-9164-1	CW9164I-B	3

Edit AP

General Interfaces **High Availability** Inventory Geolocation ICap Advanced Support Bundle

Primary Controller C9800-Primary 10.10.110.1

Secondary Controller C9800-Secondary 10.10.210.1

Tertiary Controller C9800-Tertiary 10.10.120.1

AP failover priority High ▼

# Configuration via the AP

Edit AP Join Profile

General

Client

CAPWAP

AP

Management

Security

ICap

QoS

High Availability

Advanced

CAPWAP Timers

Fast Heartbeat Timeout(sec)\*

1

Heartbeat Timeout(sec)\*

30

Discovery Timeout(sec)\*

10

Primary Discovery Timeout(sec)\*

120

Primed Join Timeout(sec)\*

0

Retransmit Timers

Count\*

5

Interval (sec)\*

3

AP Fallback to Primary ⓘ

Enable

☒

Backup Primary Controller

Name

IPv4/IPv6 Address

Backup Secondary Controller

Name

IPv4/IPv6 Address

Allows APs to fallback to the Primary WLC upon recovery

CISCO *Live!*

#CiscoLive

BRKEWN-2846

© 2023 Cisco and/or its affiliates. All rights reserved. Cisco Public

26

# Bulk Priming APs in Large Scale Deployments

## Pre-IOS XE 17.10.1

- Manually enter Primary, Secondary, and Tertiary for each AP
- Not scalable to enter console of each AP and configure this



## IOS XE 17.10.1 or Later

- Create an AP Priming Profile on the C9800 that automatically applies to APs when joining
- Scales to large numbers of APs joining the controller

# AP Priming Profile and AP Priming Filter


## AP Priming Profile

- Contains the hostname and IP address of the Primary, Secondary, and Tertiary controllers
- Primary and Secondary controllers are mandatory
- Mapped to an AP Primary Filter

## AP Priming Filter

- Similar structure as the AP filter for tag mapping
- Uses RegEx string mappings to match APs based on their configured names
- Applies the mapped AP Priming Profile to the matched APs

# AP Priming Join Flow



# Design Considerations



- Configuration via **CLI only**
  - No support via WebUI
  - Cisco DNA Center directly writes WLC IP addresses on the AP
- Max of **128** AP Priming Profiles can be configured
- Max of **1024** AP filters can be configured
  - Either for tag mapping or AP priming
  - Reduces number of AP filters available for tagging

# Configuring the AP Priming Profile

```
C9800# configure terminal
C9800(config)# wireless profile ap priming <ap-priming-profile>
C9800(config-priming)# primary <Primary WLC Name> <Primary WLC IP Address>
C9800(config-priming)# secondary <Secondary WLC Name> <Secondary WLC IP Address>
C9800(config-priming)# tertiary <Tertiary WLC Name> <Tertiary WLC IP Address>
C9800(config-priming)# priming-override
```

Overrides existing priming configurations  
**RECOMMENDED** – Not enabled by default

## Example Priming Profile:

```
wireless profile ap priming ap-priming-profile
primary C9800-Primary 10.10.110.1
secondary C9800-Secondary 10.10.210.1
tertiary C9800-Tertiary 10.10.120.1
priming-override
```

# Configuring the AP Priming Filter

```
C9800# configure terminal
C9800(config)# ap filter name <Filter Name> type priming
C9800(config-ap-pr-filter)# ap name-regex <RegEx String to Match>
C9800(config-ap-pr-filter)# profile <AP Priming Profile Name>
```

## Example Priming Filter:

```
ap filter name ap-priming-filter type priming
  ap name-regex SITE
  profile ap-priming-profile
```



# Activate AP Filter

```
C9800# configure terminal  
C9800(config)# ap filter priority <Priority Number> filter-name <Filter Name>
```

## Example Filter Priority:

```
ap filter priority 1 filter-name ap-priming-filter
```

# Statically Assign AP Priming Profile using MAC

```
C9800# configure terminal
C9800(config)# ap <MAC Address>
C9800(config-ap-tag)# profile <AP Priming Profile Name>
```

## Example Static Assignment:

```
ap aaaa.bbbb.cccc
  profile ap-priming-profile
```

# Verification


## AP Priming Profile

```
C9800# show wireless profile ap priming summary
Number of AP Priming Profiles: 1
Profile Name
-----
ap-priming-profile
```

```
C9800# show wireless profile ap priming detailed ap-priming-profile
Profile Name                : ap-priming-profile
Primary Controller Name     : C9800-Primary
Primary Controller IP       : 10.10.110.3
Secondary Controller Name   : C9800-Secondary
Secondary Controller IP     : 10.10.210.3
Tertiary Controller Name    : C9800-Tertiary
Tertiary Controller IP      : 10.10.120.3
Override                    : Enabled
```

# Configure N+1 via Cisco DNA Center

## Primary WLC



Cisco DNA Center

Provision / Network Devices / Provision Devices

Network Devices / Provision Devices

1 Assign Site 2 Configuration 3 Model Configuration 4 Advanced Configuration 5 Summary

C9800-40-ACTIVE.justloo-lab.com

Serial Number  
TTM22490UL7, TTM22480QSM

Devices  
C9800-40-ACTIVE.justloo-lab.com

WLC Role  
☒ Active Main WLC ⓘ  
☐ Anchor

Assign Interface

Interface Name	Interface Group Name	VLAN ID	IP Address
VLAN100 ⓘ	-	100	IP Address

1 Records

Rolling AP Upgrade

☐ Enable AP Reboot Percentage 25 ⓘ

Managed AP Location ⓘ

Search Hierarchy


- ☐ Global (2)
- ☐ San Jose
  - ☒ Building 14
    - ☒ Floor 1
  - ☐ Building 10

Check the boxes of the locations which the C9800 will be the Primary WLC

Cancel Save

# Configure N+1 via Cisco DNA Center

## Secondary WLC



Cisco DNA Center

Provision / Network Devices / Provision Devices

Network Devices / Provision Devices

1 Assign Site 2 Configuration 3 Model Configuration 4 Advanced Configuration 5 Summary

justloo\_9800CL.justloo-lab.com

Serial Number  
9THG1Y9Y2CT

Devices  
justloo\_9800CL.justloo-lab.com

WLC Role  
☒ Active Main WLC ☐ Anchor

Assign Interface

Interface Name	Interface Group Name	VLAN ID	IP Address
VLAN100	-	100	IP Address

1 Records

Rolling AP Upgrade

☐ Enable AP Reboot Percentage 25

Managed AP Location

Search Hierarchy

- ☐ Global (2)
- ☐ San Jose
  - ☒ Building 14
    - ☒ Floor 1
  - ☐ Building 10

Check the boxes of the locations which the C9800 will be the Secondary WLC

Cancel Save

# Verifying via the C9800 WebUI

Configuration > Wireless > Access Points

▼ All Access Points

Total APs : 7

AP Name	AP Model	S
SITE3-9120-1	C9120AXI-B	2
SITE4-9120-1	C9120AXI-B	2
SITE2-9120-2	C9120AXI-B	2
SITE2-9166-1	CW9166I-B	3
SITE1-9164-1	CW9164I-B	3

### Edit AP

General Interfaces **High Availability** Inventory Geolocation ICap Advanced Support Bundle

	Name	Management IP Address (IPv4/IPv6)
Primary Controller	C9800-Primary	10.10.110.1
Secondary Controller	C9800-Secondary	10.10.210.1
Tertiary Controller		
AP failover priority	High	

# N+1 best practices



Primary and Secondary WLC should run the same software version → No AP Image Download



Configurations should be consistent across the Primary, Secondary, and Tertiary controllers (Use Cisco DNA Center to automate)

WLANs

Profiles and Policies

Mobility Group


Policy Tag

Site Tag

RF Tag

AP-to-Tag Mappings

# N+1 best practices: Saving AP to Tag Mappings



Define tag mappings via static mappings or REGEX based on AP name / location

Save tag mapping to the AP and define tags on secondary controller

Pre-17.6.1: Manually write the tags to each AP

17.6.1 and Later: Automatically write tags to the APs via AP Tag Persistence



# N+1 best practices: AP to Tags assignment

## Configuring AP Tag Persistency (SW >17.6)

- From 17.6.1 this is supported in CLI in global configuration mode:

```
C9800(config)#ap tag persistency enable
```

- 17.6.2 and 17.7 adds support from GUI

**Note:** This will enable writing tags to the AP as it joins. For this to be applied to existing APs joined to the C9800, they will need to rejoin the WLC (CAPWAP restart)

Configuration > Tags & Profiles > Tags

Policy Site RF **AP**

**Tag Source** Static Location Filter

Priority	Tag Source	Status
0	Static	<input checked="" type="checkbox"/>
1	Location	<input checked="" type="checkbox"/>
2	Filter	<input checked="" type="checkbox"/>
3	AP	<input checked="" type="checkbox"/>

ⓘ Drag and Drop Tag Sources to change priorities

Revalidate Tag Sources on APs ☐


**Enable AP Tag Persistency** ☒

Apply

# High Availability Stateful Switchover (HA SSO)

# High Availability Stateful Switchover (HA SSO)


- Pair of 9800 in Active and Hot-Standby appear as a single WLC to the network
- All configuration synced between the pair for seamless, stateful switchover
- Clients and APs do not disconnect



AP failover takes order of sub seconds

# High Availability Stateful Switchover (HA SSO)

- Pair of 9800 in Active and Hot-Standby appear as a single WLC to the network
- All configuration synced between the pair for seamless, stateful switchover
- Clients and APs do not disconnect




AP failover takes order of sub seconds

# HA SSO behavior

## Redundancy Port (RP)


### Redundancy Port (RP)

- Syncs configuration and AP/Client databases between Active and Standby
- Monitors status of the chassis
- Possible single point of failure



# High Availability (SSO) on C9800-40/80

A direct physical connection between Active and Standby Redundant Ports or Layer 2 connectivity is required to provide stateful redundancy within or across datacenters



Sub-second failover and zero SSID outage

The only supported SFPs on Gigabit RP port are : GLC-SX-MMD and GLC-LH-SMD

# High Availability (Client SSO) on Catalyst 9800-L

A direct physical connection between Active and Standby Redundant Ports or Layer 2 connectivity is required to provide stateful redundancy within or across datacenters.

**Note:** There is no Fiber RP Port on 9800-L.

C9800-L Copper

Active Wireless Controller

Hot-Standby Wireless Controller

C9800-L Fiber

Active Wireless Controller


Redundancy Port Connectivity  
RP Via L2

Hot-Standby Wireless Controller


Sub-second failover and zero SSID outage

# High Availability (SSO) on Catalyst 9800-CL

## Intra-Host Redundancy



## Inter-Host Redundancy





# HA SSO behavior


## Redundancy Management Interface (RMI) + RP



Recommended

### RMI + RP

- With RP only, there is no way to know if the peer is down or there is a link issue
- RMI is introduced for:
  - Default Gateway check
  - Status of peer through the network
  - Dual Active Detection
- Configure it in same subnet as the Wireless Management Interface (WMI)
- RMI can be used for remote management of the standby (SSH, Programmability)
- IPv6 support introduced in 17.3.2



# SSO configuration using RMI+RP option



Recommended

Search Menu Items

- Dashboard
- Monitoring >
- Configuration >
- Administration >
- Licensing
- Troubleshooting

Walk Me Through >

Administration > Device

General

FTP/SFTP/TFTP

Redundancy

Redundancy Configuration

Redundancy Pairing Type

RMI IP for Chassis 1\*

RMI IP for Chassis 2\*

Management Gateway Failover

Gateway Failure Interval (seconds)

Local IP

Remote IP

Keep Alive Timer

Keep Alive Retries

Chassis Renumber

Active Chassis Priority\*

ENABLED

☒ RMI+RP ☐ RP

172.16.201.23

172.16.201.24

ENABLED

8

NA

NA

1

5

1

2

This is the box you want to become Active

RMI IP for chassis 1 and 2 (same IPs configured on both controllers)

Keepalives: 1-10 ms  
Retries: 5-10

Set the chassis # on each box

Set the higher priority (2) on the Active

# SSO configuration using RMI+RP option



Recommended

Q Search Menu Items

Dashboard

Monitoring >

Configuration >

Administration >

Licensing

Troubleshooting

Walk Me Through >

Administration > Device

General

FTP/SFTP/TFTP

Redundancy

Redundancy Configuration

ENABLED

Redundancy Pairing Type

☒ RMI+RP ☐ RP

RMI IP for Chassis 1\*

172.16.201.23

RMI IP for Chassis 2\*

172.16.201.24

Management Gateway Failover

ENABLED

Gateway Failure Interval (seconds)

8

Local IP

NA

Remote IP

NA

Keep Alive Timer

1

x 100 (milliseconds)

Keep Alive Retries

5

Chassis Renumber

2

Active Chassis Priority\*

1

This is the box you want to become Standby

Same configuration as Active

Set the other chassis # on Standby

Set the lower priority (1) on the Standby

# Verifying RMI and derived-RP configuration



Recommended

Administration > Device

Search Menu Items

Dashboard

Monitoring >

Configuration >

Administration >

Licensing

Troubleshooting

Walk Me Through >

General

FTP/SFTP/TFTP

Redundancy

Redundancy Configuration ENABLED

Redundancy Pairing Type ☒ RMI+RP ☐ RP

RMI IP for Chassis 1\* 172.16.201.23

RMI IP for Chassis 2\* 172.16.201.24

Management Gateway Failover ENABLED

Gateway Failure Interval (seconds) 8

Local IP 169.254.201.23

Remote IP 169.254.201.24

Keep Alive Timer 1 x 100 (milliseconds)

Keep Alive Retries 5

Chassis Renumber 1

Active Chassis Priority\* 2

Standby Chassis Priority\* 1

View from  
Active

RP IP address is auto-generated as  
169.254.x.x where x.x. is from the RMI IP

# SSO HA configuration verification



Recommended

Q Search Menu Items

Dashboard

Monitoring

Configuration

Administration

Licensing

Troubleshooting

Walk Me Through >

Monitoring > General > System

Inventory

Memory Utilization

CPU Utilization

Wireless Interface

Management Summary

Redundancy

General

Active Statistics

Standby Statistics

Refresh

My State

Peer State

Unit

Unit ID

Redundant Mode (Operational)

Redundancy Mode(Configured)

ACTIVE

STANDBY HOT

Primary

1

sso

sso

Redundancy State

Manual Swact

Communications

Standby Failures

Switchovers System Experienced

sso

enabled

Up

0

0

Chassis Details

Chassis	Role	MAC Address	Priority	H/W Version	Current State	IP Address	RMI IP Address	Mobility MAC Address	Image Version
*1	Active	6c31.0e7b.c600	2	V02	Ready	169.254.201.23	172.16.201.23	6c31.0e7b.c60b	17.9.1
2	Standby	c4b2.39ec.1f80	1	V02	Ready	169.254.201.24	172.16.201.24	0000.0000.0000	17.9.1

<< 1 >>

10

# Verifying RMI and derived-RP configuration

```
C9800# show chassis rmi
```

```
Chassis/Stack Mac Address : 00a3.8e23.8760 - Local Mac Address
```

```
Mac persistency wait time: Indefinite
```

```
Local Redundancy Port Type: Twisted Pair
```

				H/W	Current		
Chassis#	Role	Mac Address	Priority	Version	State	IP	RMI-IP
-----							
1	Standby	00a3.8e23.8760	2	V02	Ready	169.254.199.11	10.10.199.11
*2	Active	00a3.8e23.8900	1	V02	Ready	169.254.199.12	10.10.199.12

RP IP address is auto-generated as 169.254.x.x where x.x. is from the RMI IP

# Configuring RMI over IPv6

```
[no] redun-management interface <interface name> chassis 1 address  
<ipv6-1> chassis 2 address <ipv6-2>
```

- Enables/Disables redundancy
- Requires node reload after configuration is saved.
- The IPv6 address on RMI interface should be configured in the same subnet as the management interface.
- The wireless management IP and the RMI IP will appear as 2 distinct IPs in case of IPv6.

# Derived RP IP when RMI over IPv6

```
C9800# show chassis rmi
```

```
Chassis/Stack Mac Address : 00a3.8e23.a540 - Local Mac Address
```

```
Mac persistency wait time: Indefinite
```

```
Local Redundancy Port Type: Twisted Pair
```

Chassis#	Role	Mac Address	Priority	H/W Version	Current State	IP	RMI-IP
*1	Active	706d.1536.23c0	1	V02	Ready	169.254.254.17	2020:0:0:1::211
2	Standby	00a3.8e23.a540	1	V02	Ready	169.254.254.18	2020:0:0:1::212

Derived RP address will always be IPv4.



# Configuring HA SSO via Cisco DNA Center

Select the C9800 that will be the Active Controller

Go to Provision → Configure WLC HA

The screenshot displays the Cisco DNA Center interface, specifically the 'Provision / Inventory' section. The 'Wireless Controllers' tab is selected. A list of devices is shown, with 'C9800-40-ACTIVE.justio' selected. A red arrow points to this device. The 'Actions' menu is open, and 'Configure WLC HA' is highlighted. Another red arrow points to this option. The table below shows the status of the selected device.

Device Name	Device Family	Reachability	EoX Status	Manageability	Compliance	Health Score
C9800-40-ACTIVE.justio	Wireless Controller	Reachable	Not Scanned	Managed	Compliant	No Health

# Configuring HA SSO via Cisco DNA Center

Select the C9800 that will be Hot-Standby Controller

Set the RMI IP for the Active and Standby Controllers

Global

DEVICE WORK ITEMS

- ☐ Unreachable
- ☐ Unassigned
- ☐ Failed Provision
- ☐ Non Compliant
- ☐ Outdated Software Image
- ☐ No Golden Image
- ☐ Under Maintenance
- ☐ Security Advisories
- ☐ Marked for Replacement
- ☐ System Beacon Enabled

High Availability

Please make sure the Redundancy Management IP and Peer Redundancy Management IP are not assigned to any other network entities. If used, kindly change the IP accordingly and configure.

Primary C9800  
C9800-40-ACTIVE.justloo-lab.com

Select Secondary C9800  
C9800-40-STBY.justloo-lab.com  
Device IP: 10.10.120.7

Netmask\*  
24

Redundancy Management IP\*  
10.10.120.4

Peer Redundancy Management IP\*  
10.10.120.5

Cancel Configure HA

# Configuring HA SSO via Cisco DNA Center

Clicking on the HA Icon brings up the Redundancy Summary

The screenshot shows the Cisco DNA Center Provision/Inventory page. On the left, there's a 'DEVICE WORK ITEMS' list with checkboxes for various device states. In the center, a 'Devices (4)' list is visible. A modal window titled 'Redundancy Summary' is open, displaying the following information:

Primary WLC:	C9800-40-ACTIVE.justloo-lab.com
Secondary WLC:	C9800-40-STBY.justloo-lab.com
Unit MAC:	70:6d:15:36:3a:00
Redundancy State:	SSO
Mobility MAC:	70:6d:15:36:3a:0b
Sync Status:	Complete
Active RMI IP:	10.10.120.4
Standby RMI IP:	10.10.120.5
Gateway Monitoring:	Enabled
Recovery mode:	Not Applicable

At the bottom of the modal, it says '4 Records'. The background shows a table of devices with columns for Name, Model, and Status. The 'Status' column has a red 'Non-Compliant' icon next to one of the devices.


# RMI Default Gateway Check

# RMI Default Gateway Check

- Periodic ICMP ping to the gateway. every 1 second
- Both the active and the standby controllers use RMI IP as source IP
- 4 ICMP Echo request + 4 ARP request failures (~8 sec) = GW failure

## Post 17.4.1:

- GW failure interval is configurable – 6 to 20 seconds (Default is 8 sec)
- IPv6 only uses ICMP Echo Requests



# Default Gateway Check Configuration

```
C9800(config)# management gateway-failover enable
```

```
C9800(config)# management gateway-failover interval <interval value>
```

Post 17.4.1

Administration > Device

General

FTP/SFTP/TFTP

Redundancy

Redundancy Configuration **ENABLED**

Redundancy Pairing Type ☒ RMI+RP ☐ RP

RMI IP for Chassis 1\* 10.10.199.11

RMI IP for Chassis 2\* 10.10.199.12

Management Gateway Failover **ENABLED**

Gateway Failure Interval (seconds) 8

Local IP 169.254.199.11

Remote IP 169.254.199.12

Keep Alive Timer 1 x 100 (milliseconds)

Keep Alive Retries 5

Chassis Renumber 1

Active Chassis Priority\* 1

Standby Chassis Priority\* 2

Apply








# Verifying Default GW check command

```
C9800# show redundancy states
  my state = 13 -ACTIVE
  peer state = 8  -STANDBY HOT
    Mode = Duplex
    Unit = Primary
    Unit ID = 2
Redundancy Mode (Operational) = sso
Redundancy Mode (Configured)  = sso
Redundancy State               = sso

...

Gateway Monitoring = Enabled
Gateway monitoring interval = 10 secs
```

# Selecting the IP for Gateway Check

-  HA infrastructure will choose the static route IP that matches the RMI network.  

-  If there are multiple static routes, the route with the broadest network scope is selected.  

-  If there are multiple gateways for the same network, broadest mask and least gateway IP is chosen.  

-  If the static routes are update, the gateway IP will be reevaluated.




# Software and network failover scenarios

# Recovery Modes: Active-Recovery and Standby-Recovery

- **Recovery mode** logically means a state where the controller does not have all “resources” available to provide the service. At present, RP, RMI and Gateway are the resources. Ports will be in admin down in recovery mode, so no traffic goes through
- **Standby-Recovery**: If Gateway goes down, standby goes to standby-recovery mode. Standby means, its state is up to date with the active. But since it does not have the other resource (Gateway) it goes to Standby-Recovery. The standby shall not be in a position to take over the active functionality when it is in standby-recovery mode. Standby-Recovery will go back to Standby without a reload, once it detects that the Gateway reachability is restored.
- **Active-Recovery** is when the RP goes down. Active-Recovery does not have its internal state in sync with the Active. Active-Recovery **\*must\*** reload when RP comes up so that it can come up as Standby (with bulk sync).

# Software Fault Handling

- If the standby controller crashes, it shall reboot and come up as standby. Bulk sync will follow, and the standby will become hot.



- If the active controller crashes, the standby becomes active. The new active shall assume the role of active and try to detect a dual active.



# Software failure scenarios

Trigger	RP Link Status	Peer Reachability through RMI	Switchover	Result
Critical Process crash	Up	Reachable	Yes	Switchover happens
Forced switchover	Up	Reachable	Yes	Switchover happens
Critical Process crash	Up	Unreachable	Yes	Switchover happens
Forced switchover	Up	Unreachable	Yes	Switchover happens
Critical Process crash	Down	Reachable	No	No action, one controller will be in recovery mode already.
Forced switchover	Down	Reachable	N/A	No action, one controller will be in recovery mode already.
Critical Process crash	Down	Unreachable	No	Double fault – as mentioned in Network Error handling
Forced switchover	Down	Unreachable	N/A	Double fault – as mentioned in Network Error handling

# Network failure scenarios

RP Link	Peer reachability through RMI	Gateway From Active	Gateway from Standby	Switchover	Result
Up	Up	Reachable	Reachable	No	No action
Up	Up	Reachable	Unreachable	No	No Action. Standby is not ready for SSO in this state as it does not have gateway reachability. The standby shall be shown to be in standby-recovery mode. If the RP goes down, standby (in recovery mode) shall become active.
Up	Up	Unreachable	Reachable	Yes	Gateway reachability message is exchanged over the RMI + RP links. Active shall reboot so that standby becomes active.
Up	Up	Unreachable	Unreachable	No	With this, when the active SVI goes down, so will the standby SVI. A switchover is then triggered. If the new active discovers its gateway to be reachable, the system shall stabilise in Active - Standby Recovery. Otherwise, switchovers will happen in a ping-pong fashion.

# Network failure scenarios contd.

RP Link	Peer reachability through RMI	Gateway From Active	Gateway from Standby	Switchover	Result
Up	Down	Reachable	Reachable	No	No Action
Up	Down	Reachable	Unreachable	No	Standby is not ready for SSO in this state as it does not have gateway reachability. Standby will go to recovery mode as LMP messages are exchanged over the RP link also.
Up	Down	Unreachable	Reachable	Yes	Gateway reachability message is exchanged over RP link also. Active shall reboot so that standby becomes active.
Up	Down	Unreachable	Unreachable	No	With this, when the active SVI goes down, so will the standby SVI. A switchover is then triggered. If the new active discovers its gateway to be reachable, the system shall stabilise in Active - Standby Recovery. Otherwise, switchovers will happen in a ping-pong fashion.

# Network failure scenarios contd.

RP Link	Peer reachability through RMI	Gateway From Active	Gateway from Standby	Switchover	Result
Down	Up	Reachable	Reachable	Yes	Standby will become active with (old) active going to active-recovery. Config mode is disabled in active-recovery mode. All interfaces will be ADMIN DOWN with the wireless management interface having RMI IP. The controller in Active Recovery will reload to become standby when the RP link comes UP.
Down	Up	Reachable	Unreachable	Yes	Same as above
Down	Up	Unreachable	Reachable	Yes	Same as above
Down	Up	Unreachable	Unreachable	Yes	Same as above


# Network failure scenarios contd.

RP Link	Peer reachability through RMI	Gateway From Active	Gateway from Standby	Switchover	Result
Down	Down	Reachable	Reachable	Yes	Double fault – this may result in a network conflict as there will be 2 active controllers. Standby becomes active. Old active also exists. Role negotiation has to happen once the connectivity is restored and keep the active that came up last
Down	Down	Reachable	Unreachable	Yes	Same as above
Down	Down	Unreachable	Reachable	Yes	Same as Above
Down	Down	Unreachable	Unreachable	Yes	Same as Above



# RMI down during bootup

- Note that the RMI is down during boot up. If RP is also down during boot up, it is similar to the case illustrated below.



- The system is in the same state as during a double fault. There is no graceful handling of double faults. The system recovers from this state by checking the timestamps since the controller became active. The controller that has been active for a longer duration shall go to Recovery state.
- Recommendation: Connect RP ports before configuring SSO

# Dual Active Detection

# Active selection for GW reachability loss handling

Comments	State of Controller 1	State of Controller 2	Active
Scenario: Working condition with no faults	Active	Standby	Active (Controller 1)
Scenario: RP link down with RMI link up	Active	Active in Recovery Mode	Active (Controller 1)
Scenario: RP link and RMI link are down. Each controller does not know about the existence of the other – split brain condition	Active	Active	Both are active
Scenario: System that has auto-recovered from the split brain condition.	Active	Standby	Active (Controller 1)
Scenario: RP link down and hence standby became active. Previous active still exists. The old active will finally go to Recovery State – same as (2) above. The latest active is the active here as in cases where GARP is used to claim the management IP, the IP will belong to the latest active.	Active	Active	Latest Active


# HA SSO – Managing Standby WLC

# High Availability Stateful Switchover (HA SSO)

## Managing Standby WLC directly:

- Use IOS XE CLI show commands, SSH, programmable interfaces (Netconf, RESTCONF, etc.) or SNMP to monitor the status off the Standby
- For SNMP, only OIDs from IF-MIB are officially supported (ifDescr, ifOperStatus)
- To enable console port access, from active configure:  

```
redundancy  
mode sso  
main-cpu  
standby console enable
```
- For SNMP and SSH (including Netconf/RESTCONF) use RMI interface
- If external server is configured on active, syslog messages are sent also from the Standby RMI (IOS XE > 17.5)
- **SP port is not available** on Standby WLC



# High Availability Stateful Switchover (HA SSO)

## Managing Standby WLC directly:

With Netconf/RESTCONF, you can get interfaces, CPU and memory status. Login via SSH on port 830 and get the Yang models supported:

```
ssh <username>@<RMI's IP> -p 830
```

An example:

admin@172.16.201.24's password:

```
<?xml version="1.0" encoding="UTF-8"?>
```


```
<hello xmlns="urn:ietf:params:xml:ns:netconf:base:1.0">
```

```
<capabilities>
```

```
[...]
```

```
<capability>http://cisco.com/ns/yang/Cisco-IOS-XE-process-cpu-  
oper?module=Cisco-IOS-XE-process-cpu-oper&revision=2019-05-  
01</capability>
```


```
<capability>http://cisco.com/ns/yang/Cisco-IOS-XE-process-memory-  
oper?module=Cisco-IOS-XE-process-memory-oper&revision=2019-05-  
01</capability>
```



# High Availability Stateful Switchover (HA SSO)

## Managing Standby through Active WLC:

- More SNMP OIDs are available through Active (use CISCO-LWAPP-HA-MIB and CISCO-PROCESS-MIB):
  - IfName, ifAdminStatus, ifOperStatus
  - CPU (e.g., Object name: cpmCPUTotal1min)
  - Memory (e.g., Object Name: cpmCPUMemoryUsed)
  - HA Events (e.g., Object Name: cLHaPeerHotStandbyEvent)
- With Netconf/RESTCONF: info available via model Cisco-IOS-XE-ha-oper-transform.yang
- All redundancy IOS XE CLIs with “chassis standby”, example “sh env chassis standby” or show platform software process slot chassis standby, etc.



# HA SSO Best Practices



# SSO best practices

## Forming SSO Pair

### Appliance Type

- Physical Appliances: Use exact same hardware model
  - C9800-L-C cannot pair with C9800-L-F
- C9800-CL Private Cloud: Pick same scale (Large, Medium, or Small) and throughput (Normal or High) template for both VMs

### Software

- Both boxes are running the same software and in the same boot mode
- **Install mode is recommend**


### Configurations

- Set keep-alive retries to 5
- Set the higher priority (2) on the chassis that should be active
- For RMI+RP, renumber chassis prior to configuring to avoid Active-Active

# SSO best practices

## Back-to-Back Redundancy Port Connections

- For back-to-back RP connections on C9800-40/80:
  - 30 meters or Less (~100 feet): Use copper cable
  - Greater than 30 meters: Use fiber cable



# SSO best practices

## C9800-CL Private Cloud with vMotion

vMotion is supported for C9800-CL with caveats



### vMotion

- Do not run vMotion on both active and standby simultaneously



### Networking

- RP port keepalive timer set to 3 (3 x 100ms) – default is 1
- vSwitch Virtual Guest Tagging (VGT): Initiate traffic from WLC to update ARP table for uplink switch
- SR-IOV does not supported for vMotion and Snapshot



### Storage

- Local Storage: RAID 0
- Remote Storage: Less than 10ms latency and 10G link

# vMotion: Requirements

- Use recommended tested software releases:
  - ESXi vCenter 6.7
  - C9800-CL software 17.9.2 and above
- Latency (RTT) between the remote storage to the server where C9800-CL is running should be < 10 ms
- C9800-CL VM shouldn't have any ESXi host specific mapping like CD/DVD, serial console port connection, etc.
- VMware guidelines:
  - Host, remote shared storage and networking configuration:  
<https://docs.vmware.com/en/VMware-vSphere/6.7/com.vmware.vsphere.vcenterhost.doc/GUID-D19EA1CB-5222-49F9-A002-4F8692B92D63.html>
  - Networking requirements:  
<https://docs.vmware.com/en/VMwarevSphere/6.7/com.vmware.vsphere.vcenterhost.doc/GUID-3B41119A-1276-404B-8BFB-A32409052449.html>

# vMotion testing results : C9800-CL Standalone

Test	vMotion type	Observations/Comments
1	Compute resource only	<b>Caveat:</b> APs and clients drop seen, which recover after some time, due to Virtual Guest Tagging (802.1q VLAN) issue: <a href="https://kb.vmware.com/s/article/2113783">https://kb.vmware.com/s/article/2113783</a> <b>Workaround:</b> Start continuous ping from the controller to any wired network device
2	Storage only	<b>Supported:</b> APs and Clients are stable, single ping drop is seen
3	Compute resource and storage	<b>Caveat:</b> APs and clients drop seen, which recover after some time, due to Virtual Guest Tagging (802.1q VLAN) issue: <a href="https://kb.vmware.com/s/article/2113783">https://kb.vmware.com/s/article/2113783</a> <b>Workaround:</b> Start continuous ping from the controller to any wired network device

# vMotion testing results: Active C9800-CL


Test	vMotion type	Observations/Comments
1	Compute resource only	<b>Supported:</b> APs and Clients are stable, single ping drop is seen on active, standby also stable
2	Storage only	<b>Supported:</b> APs and Clients are stable, single ping drop is seen on active, stand also stable
3	Compute resource and storage	<b>Supported:</b> APs and Clients are stable, single ping drop is seen on active, stand also stable

- RP keep alive timer is set to 2 or 3 (recommended)
- The Redundancy Management Interface (RMI) is leveraged to check reachability to the gateway, and it generates the traffic that keep the MAC address table on the vswitch updated and the Virtual Guest Tagging problem doesn't happen
- Same results when Standby is moved

# Combined HA SSO and N+1

# Redundancy with HA SSO and N+1

- Highest redundancy model
- Take advantage of sub-second failover
- Redundancy in the event SSO New-Active fails before the Old-Active is recovered
- Hitless upgrades for non-ISSU releases







## 2. Upstream Switch Redundancy

# Supported SSO topologies


# Supported topologies



StackWise Pair with Split links



StackWise Pair without Split links



HSRP


Note: RP can be connected back-to-back or via L2 switches

# StackWise Pair with split links

## SSO HA Pair



Recommended




- For SSO HA, connect the Standby in the same way (same ports)
- Single L2 port-channel on each box. Ports connected to Active, and ports connected to Standby must be put in different port-channel
- Enable dot1q to carry multiple VLANs
- Make sure that switch can scale in terms of ARP and MAC table entries

**Note:** Spread the uplinks across the StackWise pair and connect the RP back-to-back (no L2 network in between)

# Dual Distribution Switches with HSRP

## SSO HA Pair



- For SSO HA, connect the Standby in the same way
- Single L2 port-channel on each box. Ports connected to Active and ports connected to Standby must be put in different port-channel
- **Port-channel PAGP and LACP supported**
- Enable dot1q to carry multiple VLANs
- Make sure that switch can scale in terms of ARP and MAC table entries

# 3. Link Level Redundancy


# LAG support with LACP and PAGP

# LACP, PAGP support in SSO Pair



# Platforms supported


- Cisco Catalyst 9800-L, 9800-40, 9800-80 (including module ports)
- Cisco Catalyst 9800-CL Private Cloud (Release 17.5.1 and later) - SR-IOV only




# LAGP, PAGP support in SSO Pair

- LACP protocol (IEEE 802.3ad) aggregates physical Ethernet interfaces by exchanging the Link Aggregation Control Protocol Data Units (LACPDU) between two devices.
- LAGP, PAGP support is needed on SSO pair in order to have:
  - 1: Ability to detect and monitor the link/connectivity failures on STANDBY.
  - 2: Seamless transfer of client data traffic upon switchover (SSO)


# Supported LACP, PAGP topologies



StackWise Pair with Split links



StackWise Pair without Split links



HSRP

# Not supported for LACP, PAGP topologies

- Auto-LAG is not supported.
- C9800-CL (w/o SR-IOV) and EWC on AP is not supported.
- L3 port-channel is not supported.
- SSO pair connected to a single switch is not recommended.

# Configuring the Port Channel on C9800 HA SSO Example

```
C9800# configure terminal
C9800(config)# interface TenGigabitEthernet0/0/0
C9800(config-if)# switchport mode trunk
C9800(config-if)# channel-group 1 mode active

C9800(config)# interface TenGigabitEthernet0/0/1
C9800(config-if)# switchport mode trunk
C9800(config-if)# channel-group 1 mode active

C9800(config)# interface Port-channel 1
C9800(config-if)# switchport mode trunk
```

Configurations on active and standby are synced and will be identical

# Configuring the Port Channel on Upstream Switch

## Example

```
Switch# configure terminal
Switch(config)# interface range TenGigabitEthernet 1/0/37-38
Switch(config-if)# switchport mode trunk
Switch(config-if)# channel-group 11 mode Active
```

Connection to Active

```
Switch(config)# interface Port-channel 11
Switch(config-if)# switchport mode trunk
```

```
Switch(config)# interface range TenGigabitEthernet 1/0/39-40
Switch(config-if)# switchport mode trunk
Switch(config-if)# channel-group 12 mode Active
```

Connection to Standby

```
Switch(config)# interface Port-channel 12
Switch(config-if)# switchport mode trunk
```

Connections to the Active and Standby Chassis must be kept on separate Port Channels (stack or not)

# Multi-chassis LAG Support

# Why Multi-chassis LAG?

- Multi-chassis LAG gives the capability to connect multiple uplinks from controller to separate uplink switches.
- **Flexibility in connecting** controller(s) to switch infrastructure.
- **VLAN-based traffic splitting** when connected to a multi-switch topology, for e.g., to isolate Guest traffic on completely different switch/network from Enterprise traffic.
- Multi-chassis LAG is supported with LAG mode ON and dynamic LAG (LACP and PAGP)



# Supported platforms

- Catalyst 9800-L, 9800-40 and 9800-80 Wireless Controllers.
- Multi-chassis LAG between ports of similar capabilities (for example, 2.5G and 2.5G or 10G and 10G. 2.5G and a 10G port in a port-channel group are not supported).
- Minimum of two ports in one LAG.



Catalyst 9800-L




Catalyst 9800-40




Catalyst 9800-80

# Supported topologies

Single controller w/ Multi-chassis LAG




SSO Pair w/ Multi-chassis LAG



Note: You can connect LAG to a single switch, However different VLANs must be connected to different LAGs


# Multi-chassis LAG with separated VLANs




- Use case: map SSIDs to different separated wired network (e.g. Guest traffic to a separated switch/network)
- Dual uplink (port-channel or single link), each with different VLANs.
- Each LAG must be connected to a single switch.
- Different VLANs must be assigned to different LAGs.
- Note: user configuration responsibility not to create a loop

# Supported LAG grouping on 9800-L

- Best practice is to have ports of same type and speed in the port channel



9800-L-C with 2.5G/1G and 10G/mGig ports in different port channels



9800-L-F with 2.5G/1G and 10G/1G Fiber ports in different port channels

# Supported LAG grouping on 9800-80

- Best practice is to have ports of same slot in the port channel








# SSO feature matrix

Functionality	Release	Embedded controller on 9K	9800-L	9800-40	9800-80	9800-CL PVT Cloud
RMI interface with config CLI (IPv4)	17.1	Supported	Supported	Supported	Supported	Supported
Dual Active Detection	17.1	Supported	Supported	Supported	Supported	Supported
Recovery Mode	17.1	Supported	Supported	Supported	Supported	Supported
Default GW Check	17.1	Supported	Supported	Supported	Supported	Supported
LACP, PAGP support with SSO	17.1	Supported	Supported	Supported	Supported	Supported for SR-IOV
GW check IP from Static routes	17.2	Supported	Supported	Supported	Supported	Supported
Multi LAG (standalone & SSO)	17.2	Supported	Supported	Supported	Supported	No, use LAG at Hypervisor
Standby Monitoring on RMI	17.3	Supported	Supported	Supported	Supported	Supported

Note: SSO is not supported on EWC and 9800-CL Public Cloud

# 4. Access Point Redundancy

# Redundancy with the Cisco Catalyst 9136 Access Point




Dual PoE ports for hitless PoE:  
No reboot required if a port loses power

Uplink ports support:  
802.3 link aggregation for increased throughput resiliency




# PoE Redundancy with Catalyst 9136




**Note:** Ensure both switches provide the same power level and have connectivity to the WLC.

\*Can also be done with a single switch

# Quick demo!



# LAG on the Catalyst 9136



## Overview

- Allows for uplink redundancy to the upstream switch
- Combined throughput of up to 5Gbps
- Supports LAG, LACP, and PAGP


Note: LAG can be configured only between two ports of the same speed.

# Infrastructure updates

# 5. Controller Software Upgrade

# Rolling AP Update/Upgrade Infrastructure


# Rolling AP Upgrade: Neighbor AP marking



## How does it work?

- Group APs into multiple groups and upgrade one group at a time.
- Grouping is done based on RF neighbors
- Admin user can control the impact and determines the number of iterations taken and the Rolling Upgrade time
- **Candidate AP selection**
  - With  $N = 4$ : If the AP in blue is selected and 4 of its best neighbours marked unavailable for selection. The resultant selection will be about  $P = 50\%$  of APs
  - For  $P = 25\%$ ,  $N = 6$ , expected iterations all ap upgrade  $\sim 5 > \sim 1h$
  - For  $P = 15\%$ ,  $N = 12$ , expected iterations all ap upgrade  $\sim 12 > \sim 2h$
  - For  $P = 5\%$ ,  $N = 24$ , expected iterations all ap upgrade  $\sim 22 > \sim 4h$
- APs reload and re-join (AP image pre-download is used) determines the Rolling AP Upgrade time

# Rolling AP Upgrade: Neighbor AP marking



User selects % of APs to upgrade in one go [5, 15, 25]

For 25%, Neighbors marked = 6 [Expected number of iterations ~ 5]

For 15%, Neighbors marked = 12 [Expected number of iterations ~ 12]

For 5%, Neighbors marked = 24 [Expected number of iterations ~ 22]




# Client steering

Clients steered from candidate APs to non-candidate APs

802.11v BSS Transition Request → Dissociation Imminent

Clients that do not honor this will be de-authenticated before AP reload



# Rolling AP Upgrade: Client steering


Clients steered from candidate APs to non-candidate APs

802.11v BSS Transition Request →  
Dissociation Imminent

Clients that do not honor this will be de-  
authenticated before AP reload


Starting 17.11 AP stops responding to client  
probes and association (in Flex)

NEW



# N+1 Site Based Hitless Upgrade

# N+1 Site Based Hitless Upgrade



- Use new Site Filters for per-site image upgrades of APs in N+1 scenarios
- Like the previous N+1 Hitless Upgrades, APs will pre-download the images
- During site upgrades, APs will upgrade to new image in rolling fashion
- After the primary controller is upgraded, APs can move back in similar fashion

# AP upgrade workflow


- 1 Add the new IOS XE image to the controller:  
**install add file <Path to Image>**

```
install add file bootflash:IOS-VersionB.bin
```

- 2 Add the sites that will be upgraded first to the site filter:  
**ap image site-filter any-image add <Site Tag Name>**

```
ap image site-filter any-image add Site1
ap image site-filter any-image add Site2
```

- 3 Pre-download image to the APs:  
**ap image predownload**



Pre-Download:  
AP Image Version  
B

# AP upgrade workflow

4

Move APs to the new destination WLC:

```
ap image upgrade destination <Destination WLC Name>
<Destination WLC IP>
```


```
ap image upgrade destination Secondary-WLC 10.10.110.4
```

5

APs will reload with the new image and join the Secondary WLC on a rolling basis

6

As the APs successfully join the Secondary WLC, the Secondary will update the Primary WLC.



## Site Filter

Site 1

Site 2

Site 3


# AP upgrade workflow

- 7 Add further sites to the site filter:  
`ap image site-filter any-image add <Site Tag Name>`

```
ap image site-filter any-image add Site3
```

- 8 Initiate the AP image pre-download, reload with the new image, and join to the Secondary WLC in rolling fashion:  
`ap image site-filter any-image apply`

- 9 As the APs successfully join the Secondary WLC, the Secondary will update the Primary WLC.



## Site Filter

Site 1

Site 2

Site 3


# AP upgrade workflow

- 10 Upgrade the rest of the sites by clearing the site filter:  
`ap image site-filter any-image clear`

- 11 APs at the remaining sites will pre-download the image, reload with the new image, and join to the Secondary WLC in rolling fashion.

- 12 As the APs successfully join the Secondary WLC, the Secondary will update the Primary WLC.

- 13 Activate the new IOS XE image on the Primary WLC.





# Configuration via WebUI

## Mobility Tunnel

Configuration > Wireless > Mobility

Global Configuration Peer Configuration

▼ Mobility Peer Configuration

+ Add × Delete ↺

MAC Address	IP Address	Public IP	Group Name	Multicast IPv4	Multicast IPv6	Status	PMTU	SSC Hash	Data Link Encryption
a453.0e9b.3b8b	10.27.0.5	N/A	default	0.0.0.0	::	N/A	N/A	3319b53f7bd5a9ac563ee59fb83e4260daed6c6b	N/A

1 10 1 - 1 of 1 items ↺

> Non-Local Mobility Group Multicast Configuration

# Configuration via WebUI

## Mobility Tunnel

Primary Controller

Add Mobility Peer

MAC Address\*

4c42.1e3d.0ccb

Peer IPv4/IPv6 Address\*

10.27.0.11

⇌ Ping Success

Public IPv4/IPv6 Address

10.27.0.11

Group Name\*

default ▼

Data Link Encryption

☐ DISABLED

SSC Hash

Enter SSC Hash (must contain 40 characters)

Cancel

Apply to Device

MAC Address and IP Address of the WMI of the Secondary

# Configuration via WebUI

## Mobility Tunnel

### Add Mobility Peer

MAC Address\*

a453.0e9b.3b8b

Peer IPv4/IPv6 Address\*

10.27.0.5

⇌ Ping Success

Public IPv4/IPv6 Address

10.27.0.5

Group Name\*

default ▼

Data Link Encryption

☐ DISABLED

SSC Hash

Enter SSC Hash (must contain 40 characters)

Cancel

Apply to Device

Secondary Controller

MAC Address and IP Address of the WMI of the Primary

# Configuration via WebUI

## Mobility Tunnel

Configuration > Wireless > Mobility

Global Configuration

Peer Configuration

### ▼ Mobility Peer Configuration

+ Add

× Delete



	MAC Address	IP Address	Public IP	Group Name	Multicast IPv4	Multicast IPv6	Status	PMTU	SSC Hash	Data Link Encryption
	a453.0e9b.3b8b	10.27.0.5	N/A	default	0.0.0.0	::	N/A	N/A	3319b53f7bd5a9ac563ee59fb83e4260daed6c6b	N/A
<input type="checkbox"/>	4c42.1e3d.0ccb	10.27.0.11 ↔	10.27.0.11	default	0.0.0.0	::	Up	1385		Disabled

1 10

1 - 2 of 2 items

### > Non-Local Mobility Group Multicast Configuration

# N+1 Site Based Hitless Upgrade with WebUI

1 Check the box for Enable Hitless Upgrade

2 Set the Site Filter to Custom

The screenshot displays the 'Administration > Software Management' interface. On the left, the 'Software Upgrade' section is active, showing options for 'Software Maintenance Upgrade (SMU)', 'AP Service Package (APSP)', and 'AP Device Package (APDP)'. The main configuration area is titled 'Hitless Software Upgrade (N + 1 Upgrade)'. It includes the following fields:

- Upgrade Mode:** A dropdown menu set to 'INSTALL'. A note indicates 'Current Mode (until next reload): INSTALL'.
- Transport Type:** A dropdown menu set to 'Device'.
- File System:** A dropdown menu set to 'bootflash'. A note indicates 'Free Space: 18459.29 MB'.
- File Path\*:** A text input field containing '/C9800-L-universalk9\_wlc.17.11.01.SPA.bin'.
- Enable Hitless Upgrade:** A checkbox that is checked. A red arrow points to this checkbox.
- Site Filter:** A dropdown menu set to 'Custom'. A red arrow points to this dropdown.
- Site Tags\*:** An empty text input field.
- Controller IP Address (IPv4/IPv6)\*:** An empty text input field.
- Controller Name\*:** An empty text input field.

Below these fields is the 'AP Upgrade Configuration' section, which includes:

- AP Upgrade per Iteration:** A dropdown menu set to '25 %'.
- Client Steering:** A checkbox that is checked.
- Accounting Percentage:** A dropdown menu set to '90 %'.

# N+1 Site Based Hitless Upgrade with WebUI

1 Check the box for Enable Hitless Upgrade

2 Set the Site Filter to Custom

The screenshot displays the 'Administration > Software Management' interface. On the left, the 'Software Upgrade' section is active, showing options for 'Software Maintenance Upgrade (SMU)', 'AP Service Package (APSP)', and 'AP Device Package (APDP)'. The main configuration area is titled 'Hitless Software Upgrade (N + 1 Upgrade)'. It includes the following fields:

- Upgrade Mode:** A dropdown menu set to 'INSTALL'. A note indicates 'Current Mode (until next reload): INSTALL'.
- Transport Type:** A dropdown menu set to 'Device'.
- File System:** A dropdown menu set to 'bootflash'. A note indicates 'Free Space: 18459.29 MB'.
- File Path\*:** A text input field containing '/C9800-L-universalk9\_wlc.17.11.01.SPA.bin'.
- Enable Hitless Upgrade:** A checkbox that is checked. A red arrow points to this checkbox.
- Site Filter:** A dropdown menu set to 'Custom'. A red arrow points to this dropdown.
- Site Tags\*:** An empty text input field.
- Controller IP Address (IPv4/IPv6)\*:** An empty text input field.
- Controller Name\*:** An empty text input field.

Below these fields is the 'AP Upgrade Configuration' section, which includes:

- AP Upgrade per Iteration:** A dropdown menu set to '25 %'.
- Client Steering:** A checkbox that is checked.
- Accounting Percentage:** A text input field set to '90 %'.

# N+1 Site Based Hitless Upgrade with WebUI

1 Check the box for **Enable Hitless Upgrade**

2 Set the Site Filter to **Custom**

3 Select the required **Site Tags**

4 Set the Secondary Controller's **IP Address** and **Hostname**

Administration > Software Management

**Software Upgrade**

Software Maintenance Upgrade (SMU)

AP Service Package (APSP)

AP Device Package (APDP)

Upgrade Mode: **INSTALL** (Current Mode (until next reload): INSTALL)

Transport Type: **Device**

File System: **bootflash** (Free Space: 18459.29 MB)

File Path\*: **/C9800-L-universalk9\_wlc.17.11.01.SPA.bin**

**Hitless Software Upgrade (N + 1 Upgrade)**

Enable Hitless Upgrade: ☒

Site Filter: **Custom**

Site Tags\*: **SITE1** **SITE2**

Controller IP Address (IPv4/IPv6)\*:

Controller Name\*:

**AP Upgrade Configuration**

AP Upgrade per Iteration: **25 %**

Client Steering: ☒

Accounting Percentage: **90 %**

# N+1 Site Based Hitless Upgrade with WebUI

5 Set the required AP Upgrade per Iteration

6 Check the box to enable Client Steering

7 Choose the required Accounting Percentage and Accounting Action

8 Set the Iteration Expiry

9 Click Download & Install

The screenshot shows the 'Hitless Software Upgrade (N + 1 Upgrade)' configuration page in the Cisco WebUI. The page is divided into several sections:

- File System:** A dropdown menu set to 'bootflash' with 'Free Space: 18459.29 MB' displayed next to it.
- File Path\*:** A text input field containing '/C9800-L-universalk9\_wlc.17.11.01.SPA.bin' and a file selection icon.
- Hitless Software Upgrade (N + 1 Upgrade):**
  - Enable Hitless Upgrade:** A checkbox that is checked.
  - Site Filter:** A dropdown menu set to 'Custom'.
  - Site Tags\*:** Two tags, 'SITE1' and 'SITE2', each with a close button (X).
  - Controller IP Address (IPv4/IPv6)\*:** A text input field containing '10.27.0.11'.
  - Controller Name\*:** A text input field containing 'C9800-40-SSO'.
- AP Upgrade Configuration:**
  - AP Upgrade per Iteration:** A dropdown menu set to '25 %'.
  - Client Steering:** A checkbox that is checked.
  - Accounting Percentage:** A text input field set to '90 %'.
  - Accounting Action:** A button labeled 'IGNORE'.
  - Iteration Expiry:** A text input field set to '9 minutes'.
- Buttons:** At the bottom, there are two buttons: 'Download & Install' (blue) and 'Save Configuration & Activate' (light blue).

Red arrows point to the 'AP Upgrade per Iteration' dropdown, the 'Client Steering' checkbox, the 'Accounting Percentage' input field, the 'Iteration Expiry' input field, and the 'Download & Install' button.



# N+1 Site Based Hitless Upgrade with WebUI

10

Monitor the progress of the entire upgrade in the **Status** Window

11

Click **AP Upgrade Statistics** to track each iteration of AP upgrade

There is an AP predownload/upgrade operation in progress. Please wait till it completes...

Upgrade Mode:  Current Mode (until next reload): INSTALL

Transport Type:

File System:  Free Space: 17214.04 MB

File Path\*:

**Hitless Software Upgrade (N + 1 Upgrade)**

Enable Hitless Upgrade: ☒

Site Filter:

Site Tags\*:

Controller IP Address (IPv4/IPv6)\*:

Controller Name\*:

**Status**

- ✓ Download Image/Package  
C9800-L-universalk9\_wlc.17.11.01.SPA.bin
- ✓ Install Image/Package
- ✓ Update Site Filter
- ✓ AP Image Predownload  
Total: 16  
Initiated: 0  
Predownloading: 0  
Completed predownloading: 8  
Failed to predownload: 0
- ⌚ AP Image Upgrade and Move...  
Percentage complete: 0
- Activate Image/Package
- Commit

[AP Upgrade Statistics](#)

# N+1 Site Based Hitless Upgrade with WebUI

10

Monitor the progress of the entire upgrade in the **Status** Window

11

Click **AP Upgrade Statistics** to track each iteration of AP upgrade

12

Wait for the current iteration of APs to finish moving to the secondary controller

AP Upgrade Statistics		
Upgrade Status	:	In Progress
Percentage Complete	:	25
From Version	:	17.9.3.50
To Version	:	17.11.0.155
Started at	:	05/17/2023 12:51:05 PST
Expected time of completion	:	05/17/2023 12:57:05 PST
Number of APs		
Upgraded	:	2
In Progress	:	2
Remaining	:	4
AP Name	Radio MAC	Status
SITE2-9120-1	c064.e422.dfe0	Upgraded and Joined Member
SITE1-9162-1	ecf4.0c20.d3e0	Upgraded and Joined Member
SITE1-9166-1	10f9.20fd.bac0	In-Progress
SITE2-9120-3	c4f7.d54b.a6e0	In-Progress
SITE2-9120-4	a00f.3704.9fa0	Remaining
SITE1-9136-1	c828.e5ed.9110	Remaining
SITE1-9166-2	e438.7e43.7f20	Remaining
SITE2-9120-2	f4bd.9ea0.c7a0	Remaining
1		10
		1 - 8 of 8 items

# N+1 Site Based Hitless Upgrade with WebUI

10

Monitor the progress of the entire upgrade in the **Status** Window

11

Click **AP Upgrade Statistics** to track each iteration of AP upgrade

12

Wait for the current iteration of APs to finish moving to the secondary controller

13

Once done, add the next Site Tag(s) to the Site Filter and click **Update Site Filter**

## Manage

[Remove Inactive Files](#)

[Rollback](#)

## Status

✓ Download Image/Package  
C9800-L-universalk9\_wlc.17.11.01.SPA.bin

✓ Install Image/Package

✓ Update Site Filter

✓ AP Image Predownload

Total: 8  
Initiated: 0  
Predownloading: 0  
Completed predownloading: 8  
Failed to predownload: 0

✓ AP Image Upgrade and Move

Percentage complete: 100

➤ Activate Image/Package

➤ Commit

[Show Logs](#)

[AP Upgrade Statistics](#)

# N+1 Site Based Hitless Upgrade with WebUI

10

Monitor the progress of the entire upgrade in the **Status** Window

11

Click **AP Upgrade Statistics** to track each iteration of AP upgrade

12

Wait for the current iteration of APs to finish moving to the secondary controller

13

Once done, add the next Site Tag(s) to the Site Filter and click **Update Site Filter**

14

Repeat Steps 12 and 13 as needed

Hitless Software Upgrade (N + 1 Upgrade)

Enable Hitless Upgrade ☒

Site Filter Custom

Site Tags\* SITE1 x SITE2 x SITE3 x

Controller IP Address (IPv4/IPv6)\* 10.27.0.11

Controller Name\* C9800-40-SSO

AP Upgrade Configuration

AP Upgrade per Iteration 25 %

Client Steering ☒

Accounting Percentage 90 %

Accounting Action IGNORE

Iteration Expiry 9 minutes

Download & Install Update Site Filter Remove Site Filter Save Configuration & Activate

# N+1 Site Based Hitless Upgrade with WebUI

10

Monitor the progress of the entire upgrade in the **Status** Window

11

Click **AP Upgrade Statistics** to track each iteration of AP upgrade

12

Wait for the current iteration of APs to finish moving to the secondary controller

13

Once done, add the next Site Tag(s) to the Site Filter and click **Update Site Filter**

14

Repeat Steps 12 and 13 as needed

Hitless Software Upgrade (N + 1 Upgrade)

Enable Hitless Upgrade ☒

Site Filter Custom

Site Tags\* SITE1 x SITE2 x SITE3 x SITE4 x

Controller IP Address (IPv4/IPv6)\* 10.27.0.11

Controller Name\* C9800-40-SSO

AP Upgrade Configuration

AP Upgrade per Iteration 25 %

Client Steering ☒

Accounting Percentage 90 %

Accounting Action IGNORE

Iteration Expiry 9 minutes

Download & Install Update Site Filter

Remove Site Filter Save Configuration & Activate

# N+1 Site Based Hitless Upgrade with WebUI

15 All APs are upgraded when the **Total** is 0

### Status

- ✓ Download Image/Package  
C9800-L-universalk9\_wlc.17.11.01.SPA.bin
- ✓ Install Image/Package
- ✓ Update Site Filter
- ✓ AP Image Predownload  
Total: 0  
Initiated: 0  
Predownloading: 0  
Completed predownloading: 16  
Failed to predownload: 0
- ✓ AP Image Upgrade and Move  
Percentage complete: 100
- Activate Image/Package
- Commit

[Show Logs](#)  
[AP Upgrade Statistics](#)

# N+1 Site Based Hitless Upgrade with WebUI

15 All APs are upgraded when the **Total** is 0

16 Apply the upgrade by clicking **Save Configuration & Activate**

Hitless Software Upgrade (N + 1 Upgrade)

Enable Hitless Upgrade ☒

Site Filter Custom

Site Tags\* SITE1 x SITE2 x SITE3 x SITE4 x

Controller IP Address (IPv4/IPv6)\* 10.27.0.11

Controller Name\* C9800-40-SSO

AP Upgrade Configuration

AP Upgrade per Iteration 25 %

Client Steering ☒

Accounting Percentage 90 %

Accounting Action IGNORE

Iteration Expiry 9 minutes

Download & Install Update Site Filter

Remove Site Filter Save Configuration & Activate

# N+1 Site Based Hitless Upgrade with WebUI

15 All APs are upgraded when the **Total** is 0

16 Apply the upgrade by clicking **Save Configuration & Activate**

17 After the controller reloads, commit the upgrade by clicking **Commit**

18 If required, use the CLI to move the APs back to the primary on a site-by-site basis

Administration > Software Management

## Software Upgrade

Software Maintenance Upgrade (SMU)

AP Service Package (APSP)

AP Device Package (APDP)

Upgrade Mode

Current Mode (until next reload): INSTALL

One-Shot Install Upgrade ☐

Transport Type

File System

Free Space: 17213.58 MB

Source File Path\*

Select File

ISSU Upgrade (HA Upgrade) ☐

Download & Install

Save Configuration & Activate

Commit




# N+1 Hitless Upgrade with Cisco DNA Center

## Create Mobility Group

1 Select the Primary Controller

2 Go to Provision → Configure WLC Mobility



# N+1 Hitless Upgrade with Cisco DNA Center

## Create Mobility Group

3 Add a new Mobility Group Name

4 Click **Add** to add a new Mobility Peer

5 In the Device Details, select the **Secondary WLC** and click **Save**.

6 Click **Configure Mobility**

Configure Mobility Group

Mobility Group Name\* **rolling\_upgrade** RF Group Name\* **default** Data Link Encryption ☐

DTLS High Cipher Only ☐ Restart for DTLS Ciphers to take effect ☐

Mobility Peers

Search

Delete 0 Selected As of: May 19, 2023 8:51 AM

<input type="checkbox"/>	Device Name	IP Address	MAC Address	Manageability	Hash	Mobility Group Name
<input type="checkbox"/>	C9800-L-C-SSO.wireless-tme.com	10.27.0.5	a4:53:0e:9b:3b:8b	Managed		rolling_upgrade

Showing 1 of 1


Cancel Reset Mobility **Configure Mobility**

# N+1 Hitless Upgrade with Cisco DNA Center

## Enable Rolling AP Upgrade

1

Select the Primary WLC and go to  
Provision → Provision Device



# N+1 Hitless Upgrade with Cisco DNA Center

## Enable Rolling AP Upgrade

1

Select the Primary WLC and go to Provision → Provision Device

2

Check the box for **Enable** choose the **AP Reboot Percentage**

3

Continue the device provisioning as normal

Cisco DNA Center

Provision / Network Devices / Provision Devices

Network Devices / Provision Devices

1 Assign Site 2 Configuration 3 Model Configuration 4 Advanced Configuration 5 Summary

C9800-40-SSO.wireless-tme.com

Serial Number: TTM2707004B, TTM22490UL7

Devices: C9800-40-SSO.wireless-tme.com

WLC Role: ☒ Active Master ☐ Anchor

☐ Skip AP Provision ⓘ

Assign Interface

Interface Name	Interface Group Name	VLAN ID	IP Address
EMPLOYEES ⓘ	-	102	IP Address

1 Records

Rolling AP Upgrade

☒ Enable ⓘ


AP Reboot Percentage: 25 ⓘ

# N+1 Hitless Upgrade with Cisco DNA Center

## Upgrading the Primary Controller

1

Go through the image upgrade procedure as normal




# Can I use HA SSO Pair with N+1 Rolling Upgrade?

Customers can stay in Secondary HA pair and reduce the upgrade process by half

Add another layer of resiliency if the N+1 chassis fails

Flexibility to upgrade each site while ensuring resiliency



# In-Service Software Upgrade (ISSU)

# Why ISSU?


Eliminate network downtime during controller upgrade process



Eliminate the need for a dedicated N+1 controller in the upgrade process



Automate the process of upgrade without manual intervention



# What is ISSU ?



Complete image upgrade from one image to another while traffic forwarding continues



All AP/Client sessions are retained during upgrade process




Pre-requisites:

- ✓ Base image is ISSU capable
- ✓ SSO pair in Active-Hot Standby
- ✓ Controllers in INSTALL mode



# Supported platforms for ISSU

## Controllers



Catalyst 9800-CL  
Private Cloud



Catalyst 9800-L



Catalyst 9800-40



Catalyst 9800-80

## Access Points



Wi-Fi 6 and 6E APs



1815W



1815I, 1815M



1832



1842



1852



2802



3802



1700, 2700, 3700,  
1570 Wave 1 APs



1540



1560




4800

Wave 2 indoor and outdoor APs

Ensure APs are supported by target software version.

# ISSU process



# Easy ISSU upgrade with WebUI!

Administration > Software Management [Click here for Latest Recommended Software](#)

**Software Upgrade**

Software Maintenance Upgrade (SMU)

AP Service Package (APSP)

AP Device Package (APDP)

Upgrade Mode:  Current Mode (until next reload): INSTALL [Manage](#)

Transport Type:  [Remove Inactive Files](#)

File System:  Free Space: 19689.41 MB [Rollback](#)

Source File Path\*  [Select File](#) 1

ISSU Upgrade (HA Upgrade) ☒ 2

Override ISSU Compatibility Check ☐

Auto terminate timer (hours)

**AP Upgrade Configuration**


AP Upgrade per Iteration

Client Steering ☒

[Download & Install](#) 3

1. Select the image you want to upgrade to
2. Enable ISSU and select % for Rolling AP upgrade
3. Click Download and Install

# Easy ISSU upgrade with WebUI!



- Monitor the progress of ISSU upgrade via the Status section in GUI
- Any important messages will trigger a popup window

# Easy ISSU upgrade with WebUI!

Administration > Software Management [Click here for Latest Recommended Software](#)

**Software Upgrade**

Software Maintenance Upgrade (SMU)

AP Service Package (APSP)

AP Device Package (APDP)

There is an AP predownload/upgrade operation in progress. Please wait till it completes...

Upgrade Mode:  Current Mode (until next reload): INSTALL

Transport Type:

File System:  Free Space: 19689.96 MB

Source File Path\*:

ISSU Upgrade (HA Upgrade) ☒

Override ISSU Compatibility Check ☐

Auto terminate timer: 05:32:26

**AP Upgrade Configuration**

AP Upgrade per Iteration:

Client Steering ☒

[Download & Install](#) [Commit](#) [ISSU Terminate](#)

**Status**

- ✓ Download Image/Package
- ✓ Install Image/Package
- ✓ AP Image Predownload
  - Total: 5
  - Initiated: 0
  - Predownloading: 0
  - Completed predownloading: 0
  - Failed to predownload: 0
- ✓ Upgrading Stand-by
- ✓ Upgrading Active
- ✓ Switchover to Stand-by
- ⚙️ AP Image Upgrade
  - Percentage complete: 16
- Commit

[Show Logs](#)  
[AP Upgrade Statistics](#)

Any time you can click on the Show Logs to see what's going on...

# Easy ISSU upgrade with WebUI!

**AP Upgrade Statistics**

Upgrade Status : In Progress  
Percentage Complete : 66

From Version : 17.9.1.8  
To Version : 17.9.3.29

Started at : 01/25/2023 14:42:08 CET  
Expected time of completion : 01/25/2023 14:48:08 CET

Number of APs  
Upgraded : 4  
In Progress : 1  
Remaining : 1

AP Name	Radio MAC	Status
C9130-SJ-1	0c75.bdb3.a7e0	Upgraded and Joined
C9130-VIM	0c75.bdb3.a820	Upgraded and Joined
AP3800E-VIM	286f.7ff1.5d40	Upgraded and Joined
C9120-Flex-2	3c41.0e2a.e640	Upgraded and Joined
C9120-Flex-1	3c41.0e2c.0660	In-Progress
C9120-SJ-1	3c41.0e2c.64e0	Remaining

1 - 6 of 6 items

Upgrade per Iteration : 25 %

Steering ☒

- During AP image upgrade, click on the dedicated link to get detailed information
- Note: APs without clients are upgraded first

```
gladius-1#sh wi cl sum  
Number of Clients: 3
```

MAC Address	AP Name	Type ID	State
1831.bf57.3e45	C9120-SJ-1	WLAN 1	Run
4ced.fb3a.d9fe	C9120-SJ-1	WLAN 1	Run
bcec.23c3.6106	C9120-SJ-1	WLAN 1	Run

```
Number of Excluded Clients: 0
```

# Easy ISSU upgrade with WebUI!

C9120-SJ-1 still not upgraded

```
sh ap upgrade
```

- Client steering happens on the AP with clients
- Once all clients are moved the AP is upgraded

```
Remaining
-----
Number of APs: 1
AP Name                      Radio MAC
-----
C9120-SJ-1                   3c41.0e2c.64e0
```

Client steering in progress...

```
gladius-1#sh wi cl summary
Number of Clients: 3

MAC Address      AP Name                      Type ID  State
-----
1831.bf57.3e45   C9120-Flex-2                 WLAN 1   Run
4ced.fb3a.d9fe   C9120-SJ-1                   WLAN 1   Run
bcec.23c3.6106   C9120-Flex-2                 WLAN 1   Run
```

```
gladius-1#sh wi cl summary
Number of Clients: 3

MAC Address      AP Name                      Type ID  State
-----
1831.bf57.3e45   C9120-Flex-2                 WLAN 1   Run
4ced.fb3a.d9fe   C9120-Flex-2                 WLAN 1   Run
bcec.23c3.6106   C9120-Flex-2                 WLAN 1   Run
```

C9120-SJ-1 upgrade started...




```
In Progress
-----
Number of APs: 1
AP Name                      Radio MAC
-----
C9120-SJ-1                   3c41.0e2c.64e0

Remaining
-----
Number of APs: 0
AP Name                      Radio MAC
-----
```





# Easy ISSU upgrade with WebUI!



- < 30 pings lost over 3k transmitted
- 0% ping loss in the whole process!!



# Upgrading HA SSO Pair using ISSU and Cisco DNA Center

1

Upload the ISSU Compatibility Matrix, if not uploaded already

2

Re-Execute the Readiness Check

**Cisco DNA Center** Image Update

### Image Update Readiness Check

**DEVICE DETAILS**

Device: C9800-40-SSO.wireless-tme.com  
Running Image: C9800-40-universalk9\_wlc.17.09.02.SPA.bin  
Golden Image: C9800-40-universalk9\_wlc.17.09.03.SPA.bin  
Reboot Required: Yes

**Readiness Checks Results** [Re-Execute Checks](#) [Export](#) As of: May 23, 2023 1:42 PM

Check Type	Description	Status	Last Checked
Config register check	<b>Expected:</b> 0x2102,0x102 <b>Actual:</b> 0x102 <b>Action:</b> No action required	✓	May 23, 2023 12:09 PM
File Transfer Check	HTTPS/SCP is reachable :10.27.0.10	✓	May 23, 2023 12:09 PM
ISSU Compatibility Check	ISSU Compatibility Check Failed. <b>Expected:</b> Compatibility Matrix must be imported for version 17.09.03 <b>Actual:</b> No Matching Compatibility Matrix found. <b>Action:</b> Import Compatibility Matrix for version 17.09.03 <a href="#">Upload Matrix</a> No file chosen	⚠	May 23, 2023 12:09 PM

[Exit](#) All changes saved [Back](#) [Next](#)

# Upgrading HA SSO Pair using ISSU and Cisco DNA Center

3 Enable ISSU Update for the Controller

4 Go through the image upgrade procedure as normal

The screenshot shows the Cisco DNA Center interface for the 'Image Update' section. The page title is 'Device Activation Order'. Below the title, there is a note: 'You can use filters to sort devices and order their activation in parallel or sequentially. After devices are sorted, you can reorder them sequentially.' The interface has two tabs: 'Parallel' (selected) and 'Sequential'. A search bar labeled 'Filter Devices' is present. Below the search bar, there is a table of devices. The table has columns: 'Device Name', 'IP Address', 'Site', 'Device Series', 'Device Role', 'Current Image', 'Update Image', and 'Comment'. One device is listed: 'C9800-40-SSO.wireless-tme.com' with IP '10.27.0.11' and Site 'Global/San Jose/Buildi...'. The 'Update Image' column shows 'C9800-40-universalk9\_...' and a green 'ISSU' button. The 'Comment' column shows 'ISSU Validation Successful Update Readiness Report'. At the bottom, there are 'Exit' and 'All changes saved' buttons, and 'Back' and 'Next' buttons.

Device Activation Order

You can use filters to sort devices and order their activation in parallel or sequentially. After devices are sorted, you can reorder them sequentially.

Device in Parallel(1) [Edit Order](#)

Parallel Sequential

Filter Devices

1 Selected [Move to Sequential Update Order](#) [ISSU](#)

Device Name	IP Address	Site	Device Series	Device Role	Current Image	Update Image	Comment
C9800-40-SSO.wireless-tme.com	10.27.0.11	Global/San Jose/Buildi...	Cisco Catalyst 9800 S...	Access	C9800-40-universalk9_...	C9800-40-universalk9_... ISSU	ISSU Validation Successful Update Readiness Report


1 Records

Show Records: 25 1 - 1

Exit All changes saved

Back Next


# ISSU official support Matrix



Supported	Not Supported
<ul style="list-style-type: none"> <li>• N +2 - Within EM release (17.9.1 &lt;&gt; 17.9.3)</li> <li>• N +2 - Across EM release (17.3.X &lt;&gt; 17.9.X)</li> </ul> <p><i>EM = Extended Maintenance release</i>  <i>SM = Standard Maintenance release</i></p>	<ul style="list-style-type: none"> <li>• Within EM release beyond +2 release</li> <li>• Across EM release beyond +2 release</li> <li>• Across software release trains (e.g., 17.12 to 18.1)</li> <li>• Within SM release (17.1.1 &lt;&gt; 17.1.2)</li> <li>• Across SM release</li> <li>• EM &lt;&gt; SM release</li> <li>• Downgrade from any release to any release</li> <li>• No support on Engineering Special (ES) releases</li> </ul>


# How can I improve AP image download time?

## Before IOS XE 17.11.1




- AP image download happens over CAPWAP Control Path
- Slow by limitation with CAPWAP window size
- Image downloads WNCd process increases CPU work-load

## After IOS XE 17.11.1



- AP image download happens over HTTPs
- Fast download speed
- Reduce CPU load and frees up CAPWAP

# Fallback to CAPWAP if HTTPs Failure



If any **failure** happens in image download over http, it will **fall back to CAPWAP** method to keep the upgrade functionality.

# Supported Platforms

- All Physical and Virtual Appliances
  - C9800-80, C9800-40, C9800-L, C9800-CL Private and Public Cloud
- Not Supported on:
  - Embedded Wireless Controller on AP

# CLI Configuration

- Enable AP image download through HTTPs

```
C9800# conf t  
C9800(config)# ap upgrade method https
```

- Customize the HTTPs port number (default is 8443)

```
C9800(config)# ap file-transfer https port <port_number>
```

# CLI Verifications

- Verify AP image download method enabled/disabled

```
C9800# show ap upgrade method
```

```
AP upgrade method HTTPS : Disabled
```

- Show command to verify AP file transfer port

```
C9800# show ap file-transfer https summary
```

```
Configured port           : 8443
```

```
Operational port          : 8443
```



# CLI Verifications

- Verification of ap image download over https support

```
C9800# show ap name AP2800 config general | sec Upgrade
```

```
AP Upgrade Out-Of-Band Capability : Enabled
```

- Verification of ap image download history

```
C9800# show wireless stats ap image-download
```

AP image download info for last attempt

AP Name	Count	ImageSize	StartTime	EndTime	Diff(secs)	Predownload	Aborted	Method
AP_3800_1	1	60856320	11/14/22 12:31:21	11/14/22 12:32:21	59	No	No	HTTPS
AP2800	1	60856320	11/14/22 12:27:43	11/14/22 12:28:39	56	No	No	HTTPS

# 6. Software Patching Capability

# Controller and AP software upgrades



## Controller Updates

Controller update or bug fixes

SMU^



## PSIRTs, Fixes on APs

AP updates or bug fixes

AP Service Pack



## New AP Model Support

Hot-patchable support for Device Pack

AP Device Pack



Contain impact within release  
Fixes for defects and security issues  
without need to requalify a new release



Faster resolution to critical issues  
Provide fixes to critical issues found in  
network devices that are time-sensitive

# Wireless Controller SMU (Software Maintenance Update)

# Wireless Controller SMU

## Wireless Controller SMU installation Options

- Software Maintenance Update (SMU) is the ability to apply patch fixes on a software release in the customer network
- Current mechanism relies on Engineering Specials
  - Entire image is rebuilt and delivered to customer

Hot Patch  
(No Wireless Controller reboot)  
Auto Install on Standby

### Hot-Patching

Inline replace of functions  
without restarting the process

On SSO Systems, patch will be  
applied on both active and  
standby without any reload

Cold Patch  
Wireless Controller Reboot

### Cold Patching

Install of a SMU will require a  
system reload

On SSO systems, SMU updates  
can be installed on the HA Pair  
with zero downtime

# Controller SMU

## Standalone vs Redundant Wireless Controller

Hot Patch  
(No Wireless Controller reboot)  
Auto Install on Standby

Cold Patch  
Wireless Controller Reboot

Standalone  
box



No reload of Controller. AP & Client session won't be affected.



Reload controller. AP & Client sessions would be affected.

Redundant  
box



SMU activation applies patch on Active & Standby. There is no controller reload and there is no impact to AP and Client sessions.



Follows ISSU path and both Standby & Active controller reloaded but there is no impact to AP and Client session.

CLI required for ISSU

# Wireless Controller SMU

## Standalone vs Redundant Wireless Controller

- Software Maintenance Update (SMU) is the ability to apply patch fixes on a software release in the customer network
- Current mechanism relies on Engineering Special: Entire image is rebuilt and delivered to customer

### Standalone box

### Redundant box

Hot Patch  
(No Wireless Controller reboot)  
Auto Install on Standby



No reload of Controller. AP & Client session won't be affected.



SMU activation applies patch on Active & Standby. There is no controller reload and there is no impact to AP and Client sessions.

Cold Patch  
Wireless Controller Reboot



Reload controller. AP & Client sessions would be affected.



Follows ISSU path and both Standby & Active controller reloaded but there is no impact to AP and Client session.

# SMU Install via WebUI

Administration ▾ > Software Management

 [Click here for Latest Recommended Software](#)

Software Upgrade

Software Maintenance  
Upgrade (SMU)

AP Service Package  
(APSP)

AP Device Package  
(APDP)

+ Add

↺ Rollback

	Type ▾	State ▾	Filename ▾
<input type="radio"/>	SMU	Activated and Committed	bootflash:C9800-L-universalk9_wlc.17.03.05a.CSCwb45089.SPA.smu.bin

⏪ ⏩ 1 ⏪ ⏩

10 ▾ items per page

1 - 1 of 1 items

Auto terminate timer: inactive

## INSTALL COMMIT OPERATION:

```
Initiating INSTALL_COMMIT operation
install_commit: START Tue Jan 10 14:10:16 PST 2023
install_commit: Committing SMU
Executing pre scripts....
Executing pre sripts done.
--- Starting SMU Commit operation ---
Performing SMU_COMMIT on all members
  [1] SMU_COMMIT package(s) on chassis 1/R0
  [1] Finished SMU_COMMIT on chassis 1/R0
  [2] SMU_COMMIT package(s) on chassis 2/R0
  [2] Finished SMU_COMMIT on chassis 2/R0
Checking status of SMU_COMMIT on [1/R0 2/R0]
SMU_COMMIT: Passed on [1/R0 2/R0]
Finished SMU Commit operation

SUCCESS: install_commit /bootflash/C9800-L-universalk
9_wlc.17.03.05a.CSCwb45089.SPA.smu.bin Tue Jan 10 14:
10:26 PST 2023
```



# SMU ISSU Install via CLI

```
C9800# install add file flash:C9800-L-universalk9_wlc.17.03.05a.CSCwb45089.SPA.smu.bin  
install_add: START Tue Jan 10 15:01:47 PST 2023  
install_add: Adding SMU  
install_add: Checking whether new add is allowed ....
```

```
C9800# install activate file flash:C9800-L-universalk9_wlc.17.03.05a.CSCwb45089.SPA.smu.bin issu  
install_activate: START Tue Jan 10 15:03:37 PST 2023  
install_activate: Activating ISSU
```

```
C9800# install commit  
install_commit: START Tue Jan 10 15:24:23 PST 2023  
install_commit: Committing SMU
```

# Per-site & Per- AP Model AP Service Pack

# Per-site / Per-model AP Service Pack



Supported on all platforms and all deployment scenarios (Flex, Local and Fabric)




Pre-downloaded to and activated on the affected AP models only



Per-model APSP works in conjunction with site-specific rollout



**Per-AP model Service Pack**  
APSP can have a subset of APs that are affected by the update



**Update on Subset APs**  
Fix applied on a subset of APs in the deployment using a site-filter



**Controlled Propagation**  
Enables user to control the propagation of APSP in the network

# APSP workflow

Applying APSP for 9115/9120 APs on per-site and per-model basis

```
ap image site-filter file APSP1 add SiteA
```

Install prepare activate

Install activate


Install commit

```
ap image site-filter file APSP1 add Site B
```

```
ap image file APSP1 site-filter apply
```

Not applicable for building with 9130AX

Apply on Site A in rolling AP fashion



# AP Device Pack (APDP)

# AP Device Pack

Traditionally ...



New AP hardware models need new WLC software



Wait for CCO version and re-qualify new release



Plan for Upgrading entire network



**Contain Impact within release**  
Deploy new hardware without need to requalify a new controller release




**Reduce Lifecycle delays**  
Faster deployment of latest AP hardware and technology




**Zero Network Downtime**  
Applied as HOT patch on the controller with no service impact for APs and Clients

With AP Device Packs

# APDP installation workflow



# APDP installation workflow




Note: Fixes for the AP installed via APDP will be via AP Service packs like a baseline supported AP.



# Installing SMU, APDP, APSP with Cisco DNA Center

## 1 Import/Download SMU/APDP/APSP into inventory



# Installing SMU, APDP, APSP with Cisco DNA Center

1 Import/Download SMU/APDP/APSP into inventory

2 Click Add On for the required software version

Design / Image Repository / Image Family

< Image Repository

Cisco Catalyst 9800-40 Wireless Controller

SUMMARY

- > Roles & Tags (6)
- > Major Versions (10)
- > Golden Images (2)

Images (11) [Show Tasks](#)

Search Table

Image Name	Version	Devices	Advisories	Golden Image
<a href="#">C9800-40-universalk9_wlc.17.06.04.SPA.bin</a> Verified	17.06.04.0.4912 Add On (N/A)	0	0 Critical 0 High	☆
<a href="#">C9800-40-universalk9_wlc.17.07.01.SPA.bin</a>	Cupertino-17.7.1 (Latest) Add On (N/A)	0	0 Critical 2 High	↓
<a href="#">C9800-40-universalk9_wlc.17.09.01.SPA.bin</a> Verified	17.09.01.0.178 Add On (N/A)	0	0 Critical 5 High	☆
<a href="#">C9800-40-universalk9_wlc.17.09.02.SPA.bin</a> Verified	17.09.02.0.3040 <a href="#">Add On (1)</a>	0	0 Critical 0 High	★
<a href="#">C9800-40-universalk9_wlc.17.10.01.SPA.bin</a> Verified	17.10.01.0.1444 Add On (N/A)	0	0 Critical 0 High	☆
<a href="#">C9800-40-universalk9_wlc.17.06.04.SPA.bin</a>	17.06.04.0.4912	0	0 Critical 0 High	☆

# Installing SMU, APDP, APSP with Cisco DNA Center

1 Import/Download SMU/APDP/APSP into inventory

2 Click Add On for the required software version

3 Mark it as Golden, additionally to Golden Image

4 Go through the image upgrade procedure

Design / Image Repository / Image Family

Controller

Add On List (1)

BASE IMAGE INFORMATION

Family Cisco Catalyst 9800-40 Wireless Controller

Image Name C9800-40-universalk9\_wlc.17.09.02.SPA.bin

SMU (0) Sub-package (0) ROMmon (0) **APSP (1)** APDP (0)

C9800-universalk9\_wlc.17.09.02.CSCwd87612.SPA.apsp.bin

ADD ON ATTRIBUTES

Description Cisco IOS-XE Patch package

Defect Id CSCwd87612

Reboot Required No

Category bulk-patch

Supercedes Not Available

Compliant Devices Not Available

Image Verification Unable to verify  
Only production images on cisco.com can be verified.  
[Click Here](#) to update the known image meta-data.  
*Note: Controlled Cisco images cannot be verified at the moment.*

Golden Image ☐

Device Roles/Tags Role: All

# Achieving the zero downtime win!



## Unplanned Events

- ✓ Stateful switchover with an active standby
- ✓ N+1 redundancy for always-on network, services, and clients
- ✓ LAG on WLC and APs



## Infrastructure Updates

- ✓ Patching capability with SMU and APSP for wireless controllers and APs
- ✓ APDP and flexible per-site updates contain impact area




## Image Upgrades

- ✓ ISSU for Seamless Upgrades
- ✓ N+1 rolling AP upgrades help ensure seamless client connectivity

# References

- Cisco Catalyst 9800 Wireless Controller High Availability SSO Deployment Guide:  
<https://www.cisco.com/c/dam/en/us/td/docs/wireless/controller/9800/17-5/deployment-guide/c9800-ha-sso-deployment-guide-rel-17-5.pdf>
- Cisco Catalyst 9800 Wireless Controller N+1 High Availability Deployment Guide:  
<https://www.cisco.com/c/dam/en/us/td/docs/wireless/controller/9800/17-4/deployment-guide/c9800-n-plus-1-high-availability-wp.pdf>
- High Availability Using Patching and Rolling AP Upgrade on Cisco Catalyst 9800 Series Wireless Controllers: [https://www.cisco.com/c/dam/en/us/td/docs/wireless/controller/technotes/8-8/Cisco Catalyst 9800 Series Wireless Controllers Patching.pdf](https://www.cisco.com/c/dam/en/us/td/docs/wireless/controller/technotes/8-8/Cisco_Catalyst_9800_Series_Wireless_Controllers_Patching.pdf)

# Fill out your session surveys!



Attendees who fill out a minimum of four session surveys and the overall event survey will get **Cisco Live-branded socks** (while supplies last)!



Attendees will also earn 100 points in the **Cisco Live Challenge** for every survey completed.



These points help you get on the leaderboard and increase your chances of winning daily and grand prizes



# Continue your education



- Visit the Cisco Showcase for related demos
- Book your one-on-one Meet the Engineer meeting
- Attend the interactive education with DevNet, Capture the Flag, and Walk-in Labs
- Visit the On-Demand Library for more sessions at [www.CiscoLive.com/on-demand](https://www.CiscoLive.com/on-demand)



The bridge to possible

# Thank you

CISCO *Live!*

#CiscoLive




# Cisco Live Challenge

Gamify your Cisco Live experience!  
Get points for attending this session!

## How:

- 1 Open the Cisco Events App.
- 2 Click on 'Cisco Live Challenge' in the side menu.
- 3 Click on View Your Badges at the top.
- 4 Click the + at the bottom of the screen and scan the QR code:



The background features a vibrant, multi-colored abstract design. On the left, there are overlapping, wavy bands of color in shades of orange, red, and yellow. On the right, a bright white light source emits a series of colorful rays in shades of blue, green, and yellow, creating a sunburst effect. The overall composition is dynamic and energetic.

CISCO *Live!*

Let's go

#CiscoLive